REGULATO INFORMATION DISTRIBUTION (RIDS)

ACCESSION NBR:8103110403 DOC.DATE: 81/03/04 NOTARIZED: NO DOCKET # FACIL:50-261 H. B. Robinson Plant, Unit 2, Carolina Power and Ligh 05000261

AUTHOR AFFILIATION

UTLEY, E.E. Carolina Power & Light Co.
RECIP.NAME RECIPIENT AFFILIATION

VARGA, S.A. Operating Reactors Branch 1

SUBJECT: Responds to NRC 810113 ltr requesting addlinfo on adequacy of electrical distribution sys voltage. Issue closely related to degraded grid voltage issue which has been closed by NRC. Requests meeting during wk of 810314 to clarify info needed.

DISTRIBUTION CODE: A0158 COPIES RECEIVED:LTR LE ENCL SIZE: LE TITLE: Onsite Emergency Power Systems

NOTES:

	RECIPIENT ID CODE/NAME:		COPIES LTTR ENCL	RECIPIENT ID CODE/NAME		COPIES LTTR ENCL	
ACTION:	VARGA,S.	04	7	•			
INTERNAL:	AEOD I&E NRC PDR OP EX EVAL BE POWER SYS BR		1 2 1 1	MPA OELD OR ASSESS BR	09 18 17 12 01	1 1 1 1 1 1	
EXTERNAL:	ACRS NSIC	16 05	16 16 1	LPDR	0.3	1	6

WAR 1 2 1981

March 4, 1981

File: NG-3514(R)

Serial No.: NO-81-400

Office of Nuclear Reactor Regulation
Attention: Mr. Steven A. Varga, Chief
Operating Reactors Branch No. 1
United States Nuclear Regulatory Commission
Washington, D. C. 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2

DOCKET NO. 50-261

LICENSE NO. DPR-23

REQUEST FOR ADDITIONAL INFORMATION
ADEQUACY OF STATION ELECTRIC DISTRIBUTION SYSTEM VOLTAGE

Dear Mr. Varga:

By letter of January 13, 1981, you requested additional information to enable you to continue your review of the adequacy of the $\rm H_{\bullet}$ B. Robinson Unit No. 2 electrical distribution system.

As you are aware, this issue is closely related to the issue concerning degraded grid voltage. Carolina Power & Light Company (CP&L) has responded to your concerns regarding degraded grid voltage and your staff has issued a safety evaluation report closing this issue. Due to the similarity in these issues, and the repetition of questions previously answered and used in the Staff's safety evaluation, CP&L is somewhat confused by your recent questions in light of our responses made to resolve the degraded grid voltage concern. We believe that a meeting between your Staff and CP&L is necessary in order to clarify what information is needed by your Staff, so that we can direct our resources more efficiently in resolving any concerns you may have. In order to avoid conflicts with the upcoming emergency planning drill at H. B. Robinson, it is requested that this meeting be held the week of March 14 or 21. We will contact the NRC Project Manager to arrange a specific date for the meeting.

Yours very truly,

E. E. Utley

Executive Vice President

Power Supply and

Engineering & Construction

SDF/dk (N#40)

cc: Mr. J. D. Neighbors

A015, 10