

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8602060231 DOC. DATE: 86/01/31 NOTARIZED: NO DOCKET #
 FACIL: 50-261 H. B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261
 AUTH. NAME AUTHOR AFFILIATION
 ZIMMERMAN, S. R. Carolina Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 RUBENSTEIN, L. S. PWR Project Directorate 2

SUBJECT: Forwards Rev 2 to XN-NF-85-103 "HB Robinson Unit 2, Cycle 11
 SAR." Refueling outage scheduled to begin 860201 & last
 approx 7 wks. refueling will be performed per 10CFR50.59(a).

"See subject file"
 DISTRIBUTION CODE: A0010 COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+53
 TITLE: OR Submittal: General Distribution

NOTES: 05000261
 OL: 07/31/70

RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
	LTTR	ENCL		LTTR	ENCL
PWR-A ADTS	1	0	PWR-A PD2 PD 01	5	5
PWR-A EB	1	1	PWR-A EICSB	1	1
PWR-A FOB	1	1	REQUA, G	1	1
PWR-A PSB	1	1	PWR-A RSB	1	1

INTERNAL: ACRS	09	6	6	ADM/LFMB	1	0
ELD/HDS1		1	0	NRR/DHFT/TSCB	1	1
NRR/DSRO/RRAB		1	1	NRR/ORAS	1	0
<u>REG FILE</u>	04	1	1	RGN2	1	1
EXTERNAL: 24X		1	1	EG&G BRUSKE, S	1	1
LPDR	03	1	1	NRC PDR	02	1
NSIC	05	1	1			

Add:

	Ltr.	Encl
NRR PWR-A ADTS	1	1
NRR / DSRO	1	1
RGN 2 / DRSS / EPRPB	1	1
RM / DDAMI / MIB	1	1

TOTAL NUMBER OF COPIES REQUIRED: LTTR 34 ENCL 30



Carolina Power & Light Company

JAN 31 1986

SERIAL: NLS-86-013

Director of Nuclear Reactor Regulation
Attention: Mr. Lester S. Rubenstein, Director
PWR Project Directorate #2
Division of Licensing - A
United States Nuclear Regulatory Commission
Washington, DC 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261/LICENSE NO. DPR-23
CYCLE 11 OPERATION
SAFETY ANALYSIS REPORT

Dear Mr. Rubenstein:

This letter is to inform you of Carolina Power & Light Company's (CP&L) plans for refueling H. B. Robinson, Unit 2 for Cycle 11 operation. The refueling outage is scheduled to begin around February 1, 1986 and last approximately seven weeks. Refueling for Cycle 11 will be performed in accordance with the provisions of 10 CFR 50.59(a) since Cycle 11 operation will involve no unreviewed safety questions and will require no change in the Technical Specifications of the plant.

In addition, this letter also transmits for your information Exxon report XN-NF-85-103, Rev. 2, "H. B. Robinson Unit 2, Cycle 11 Safety Analysis Report" dated January 1986.

If you have any questions concerning this subject, please contact Mr. Jan Kozyra at (919) 836-7924.

Yours very truly,

S. R. Zimmerman
S. R. Zimmerman
Manager

Nuclear Licensing Section

SRZ/MDM/ccc (3217MDM)

cc: Dr. J. Nelson Grace (NRC-RII)
Mr. G. Requa (NRC)
Mr. H. Krug (NRC Resident Inspector - RNP)

8602060231 860131
PDR ADOCK 05000261
P PDR

Adol
11

Add: NRR PWR-A ADTS Ltr Encl
NRR/DSRO
RCN2/DRSS/EPRPB
Rm/DAMI/MIB