July 02, 2014

A SUPERIOR ENERGY SERVICES COMPANY

L1 37-23410-01 03021037 2014001

Via e-mail and Certified Mail, Return Receipt Requested, No. 7014 0150 0002 0442 2833

United States Nuclear Regulatory Commission Region I 2100 Renaissance Blvd., Suite 100 King of Prussia, PA 19406-2713

RE: R

Reply to a Notice of Violation

NRC Inspection Report No. 03021037/20114001

AWS, Inc. DBA Titan Wireline

Dear Mr. Welling:

This correspondence is in response to the Nuclear Regulatory Commission's (NRC) letter dated June 16, 2014 and received by us on July 02, 2014 regarding alleged violations identified during your site inspection March 18, 2014. With respect to concerns identified in the report captioned above Titan Wireline Services ("Titan Wireline") will put into practice the following corrective actions.

Responses to Alleged Violations Cited:

A. 10 CFR 39.61(c) requires that the licensee shall provide safety reviews for logging supervisors and logging assistants at least once during each calendar year.

Corrective Action: Safety reviews for all logging supervisors and assistants will be conducted according to 10 CFR 39.61(c) at least once during each calendar year. The 2014 safety review has been accomplished for all logging supervisors and assistants. Copies of the safety training class rosters are enclosed as an attachment.

An electronic compliance matrix has been created to track and ensure all future safety reviews are conducted according to our NRC license requirement. A copy of the referenced matrix is enclosed as an attachment.

The target date for completion of this activity is July 31, 2014.

NMSS/RGNI MATERIALS-004

B. 10 CFR 30.34(c) requires, in part, that each person licensed by the commission pursuant to the regulations in Part 30 shall confine his possession and use of the byproduct material to the locations and purposes authorized in the license.

NRC License No. 37-23410-01, Condition No. 18 states, in part, that the licensee will conduct its program in accordance with the statements, representations, and procedures contained in the documents, including any enclosures listed below, including the license application dated March 31, 2004. Section 10.5.A of the license application states that "Annual unannounced inspections of all logging supervisors will be conducted by the RSO and or ARSO to determine compliance with regulations and written operating and safety procedures."

Corrective Action: Annual unannounced compliance inspection of all authorized users will be conducted by the Company's RSO or ARSO. The purpose of the assessment is to identify any gaps in our radiation protection program and implement the necessary corrective actions to upgrade our procedures to ensure compliance with applicable radiation control standards contained in 10 CFR 30.34(c) and our NRC license Section 10.5A. A copy of the most recent compliance inspection is enclosed as an attachment.

An electronic compliance matrix has been created to track and ensure that annual compliance inspections are conducted in the future according to our NRC license requirements. A copy of the referenced matrix is enclosed as an attachment.

The target date for completion of this activity is July 31, 2014 or next scheduled job.

C. 10 CFR 39.61(d) states, in part, that the licensee shall maintain a record on each logging supervisors and logging assistants training and annual safety review. The training records must include copies of written tests and dates of oral tests given after July 14, 1987. The training records must be retained until three years following the termination of employment. Records of annual safety reviews must list the topics discussed and be retained for three years.

<u>Corrective Action:</u> Records of each logging supervisors and logging assistants training, annual safety review, and tests referenced in our response in item A are on file and will be maintained according to 10 CFR 39.61(d).

An electronic compliance matrix has been created to track and ensure document that all logging supervisors and assistant logging supervisors future safety reviews are tracked and conducted according to our NRC license requirements. A copy of the referenced matrix is enclosed as an attachment.

The target date for completion of this activity is July 9, 2014.

The individuals responsible for overall management of the business activities will receive awareness training that will cover radiation safety and the company's duties and responsibilities under our NRC license No. 37-23410-01 no later than July 15, 2014. Such training will be conducted by the RSO or ARSO for Warrior Energy Services Corporation License # 17-17707-

01 (parent company of Titan Wireline). The RSO and other individuals responsible for managing our radiation safety program according to the terms and conditions of our NRC license have received appropriate training. Copies of the radiological training certificates are provided as an attachment. A complete list of the employees who have or will receive the training according to these conditions is provided below.

Employee Name	Title	Training	Date	Training Provider:
Vance Byram	RSO	RSO Refresher		Applied Health Physics
Todd Riggle,	Operations Supervisor	RSO		Applied Health Physics
Robert Weiss	Operations Supervisor	Awareness Training	4	Warrior SRSO
Mark Boyer	Technician	RSO	لقاسم ساسانا	Applied Health Physics
Rick Mckee	Safety Coordinator	RSO Refresher		Applied Health Physics
Michael Daquilante	Regional Manager	Awareness Training		Warrior RSO
Timothy Rearick	Operations Manager	Awareness Training		Warrior RSO

Future plans as they exist today are to allow the U.S. Nuclear Regulatory Commission's License #37-23410-01 to expire on July 31, 2014. The material under the jurisdiction of this license will be supported and transferred to the U.S. Nuclear Regulatory Commission's License #17-17707-01. The current Radiation Safety Officer (RSO) listed on License #37-23410-01, Vance Byram, will not assume the duties of RSO under the License #17-17707-01.

It is the intention of Titan Wireline Services to demonstrate through our actions that the issues described in the Notice of Violation have been treated with the appropriate level of sincerity and thoroughness as to avoid reoccurrence of similar events in the future. Titan Wireline is committed to regulatory compliance at our facility. If you require any additional or supporting information with respect to any of the issues described in this letter, please do not hesitate to contact the undersigned.

Thank you for your consideration regarding this matter.

Very truly yours.

Michael Daquilante Regional Manager Titan Wireline PO Box 286

Elderton, PA 15736

AWS / Titan Wireline Radiation History Review Matrix

					2014 Ann				
Employe First Name	ee Name Last Name	Active	Title	2014 User List	2014 Job Usuage	2014 Annual Audit	2014 Radiation Safety Training	RSO Training	RSO Refresher
Mark	Boyer		Technician	, , , , , , , , , , , , , , , , , , ,					
Vance	Byram		RSO -	File of the second					
Michael	Daquilante		Regional Mgr						
Norman Rick	McKee		Safety Coordinator						
Timothy	Rearick		Ops. Mgr.						
Todd	Riggle .		Ops. Supv.			Andrew Service	444 % 41 4 4 4 4		
Robert	Weiss		Ops. Supv.						

Legend



CLASS ROSTER - SAFETY REVIEWS LOGGING SUPERVISORS AND ASSISTANTS

PERSONAL INFORMATION WAS REMOVED BY NRC. NO COPY OF THIS INFORMATION WAS RETAINED BY THE NRC.

"Printed or electronic versions of this document obtained outside the Company's intranet are uncontrolled."



STANDARD CORPORATE FORM

SCF-003

TRAINING RECORD

	se Title: Radiation Sa		WESC	Date:	
nstr	uctor Name & Company:	ICK WICKEE	VYLOO	Location: 🖊	300-200
	Employee Name	Employee # or Last 4 of SSN	Division of Sub-Name	Employee Signature	Completed
1	Josh Barden		1300-200	ShiBork ,	6/5/13
2	Christopher Harkton		1300 200	Ches offer	
3	Mark Elgin		1300-2000	Shall the	
4	Roude Reddinger	<u> </u>	1300-200	Randy Kanday	
5	Robert Weiss		1300-200	9000	
7	Tale Hoog		1300-200	Town Mary	-
8	anglia ware		1300-200	Man de la company	0/3/1
9				-	
10				And the state of the	· · · · · · · · · · · · · · · · · · ·
11					
2					
13					
4					
5					
16					
17	AA-van				
18					
19				1	

HSEQ-SESI-SCF-003

Rev 0 (01-SEPT-12)

Page 1 of 1

PERSONAL INFORMATION WAS REMOVED BY NRC. NO COPY OF THIS INFORMATION WAS RETAINED BY THE NRC.

"Printed or electronic versions of this document obtained outside the Company's Intranet are uncontrolled."



STANDARD CORPORATE FORM

SCF-003

TRAINING RECORD

		PLEASE PI	RINT CLEARLY		
Cour	se Title: Radiation Sa	afety		Date:	5/14
			WESC	Location: 6	300-200
	Employee Name	Employee # or	Payision or Sob Pane	Renployee Signature	Completed
1	BARRY McIlwain		1300-200	R	6/5/14
2	Lane Fitzgerald		1300-200		
3	David C. Overer		1300-200	Sans Coluct	
4	Josh Clark		1300 200	amblare	
5	Dan Handley		1300-200	DALI	
6	TIVSON MIRY).	1300-200	CA /	
7	JAMES MERRYMOND	7	1300-200	J. Mun)
8	Seria Lichtens	W	1300-200	Dang - Solar	10/5/14
9				00	
10					
11					
12			1	1.	
13					
14					
15					- F
16					
17					100
18					
19					
20					

PERSONAL INFORMATION WAS REMOVED BY NRC. NO COPY OF THIS INFORMATION WAS RETAINED BY THE NRC,

"Printed or electronic versions of this document obtained outside the Company's intranet are uncontrolled."



STANDARD CORPORATE FORM

SCF-003

TRAINING RECORD

PLEASE PRINT CLEARLY Course Title: Radiation Safety Instructor Name & Company: Rick McKee WESC Location: 1300- TEMPloyee Name Temployee Strumer Com Total Barden Christian Harkey Mark Elsin Rebert Lieus Total Company Total	
Instructor Name & Company: Rick McKee WESC Employee Name Imployee Suparure Company Imployee Suparure Impl	, .
1 Jash Barden 2 Christoper Harktor 3 Mark Elsin 5 Robert Weiss 6 Date tank 7 Anglaciante 8 9 10 11 12 13 14 15 16 17 18	14
1 Josh Barden 2 Christman Harpton 3 Mark Elgin 4 Randa Radingan 5 Raber Weiss 6 Date Hans 7 Organization (1200) 8 9 10 11 12 13 14 15 16 17 18	200
2 Christoper Hartonet 3 Mark Elsin 4 Rando Ratinger 5 Robert Welss 6 Date hanc 7 Organicawatt 8 9 10 11 12 13 14 15 16 17	pleted
2 Christoper Harkton 3 Mark Elgin 4 Rando Radinger 5 Robert Weiss 6 Date Hanc 7 Organization 1300-200 Mario Radinger 1300-200 Rando Radinger 1300-200	5/14
4 Rando Reducios 5 Robert Weiss 6 Date Land 7 Anglicawatt 8 9 10 11 12 13 14 15 16 17	1
5 Robert Weiss 6 Date from 7 Organicawartz 8 9 10 11 12 13 14 15 16 17	1
6 Dale Hance 1300-200 Dale David 1310-200 Marie 131	1
7 Orghowatz 330-200 100 110 11 12 13 14 15 16 17 18	1
8 9 10 11 12 13 14 15 16 17 18	
9 10 11 12 13 14 15 16 17 18	15/19
10 11 12 13 14 15 16	
11	مدارا بازدود
12 13 14 15 16 17	بنگ چستس
13 14 15 16 17 18	
14 15 16 17 18	·
15 16 17 18	
16 17 18	
17 18	· .
18	
17	- :
20	
20	
COURSE START TIME: 2:15 COURSE FINISH TIME: 2:45 COURSE DURATION: 2	
Jpon completion of training, instructor must verify by signature that all students appearing on this ro nave completed the training requirements for this date. Incomplete rosters will not be accepted and v	will be
returned to sender.	
Instructor Signature Date	
Instructor Signature Date	

HSEQ-SESI-SCF-003

Rev 0 (01-SEPT-12)

Page 1 of 1

COMPLIANCE MATRIX

		·				1	2014			2015					
Employe	e Name	Active	Title	2014 User	2014 Job	2014 Annual	2014 Radiation	RSO	RSO	2015 User	2014 Job	2014 Annual		RSO	RSO
First Name	Last Name			List	Usuage	Audit	Safety Trabing	Training	Refresher	List	Usuage	Audit	2014 Radiation Safety Training	Training	Refresher
Cory	Adams		_							1					
Ryan	Arbaugh		Ops. Supv.												
Jeffery	Armstrong		Operator												
Joshua	Barden		Skill Labor												
David	Bierer		Skill Labor												
Joseph	Boyle														
Mark	Boyer	344	Technician												
Vance	Byram		RSO					Andreys Assessment	11. 7						
Nicholas	Carney	Control per della 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				7.77									
Joshua	Clark		Operator												
Russell	Clark, Jr.		Operator												
Richard	Cramer				1.										
Michael	Daquilante	N. ee .	Regional Mgr		-		1.00								
Mark	Elgin	1 27 3	Shop Foreman				- ,								
Keith	Fleming														
Richard	Fitzgerald, Jr.		Ops. Supv.		1 1										
Lane	Fitzgerald		Operator					19							
William	Gett					1.									<u> </u>
Richard D	Haag	2 75 1	Skill Labor												
Christopher	Harkleroad		Shop Labor	<u> </u>											
lustin	Hartzell		Operator												
Daniel	Headley		Operator					-					-		
Brian	Huffman		Ops. Supv.												
Christopher	Klonowski														
lahn	King		Operator												
erry	Lichtenfels		Skill Labor					,							
shawn	Lockard	4, 11, 17, 14	Ops. Supv.												
Randy	Lukehart														
Matthew	McCormick		Operator												
Barry	Mcliwain		Skill Labor												
аппу	McLain								, ,						
Norman Rick	McKee		Safety Coordinator												
ames	Merryman		Skill Labor												
Cody	Meyer		Operator												
Villiam	Metro	-													
yson	Mish		Operator												
imothy	Monoskey		Ops. Supv.												
effrey	Nickle				- 7 W T										
V.	Orr					1 / 1 / 1 / L		1							
oseph	Ploskunak														
	Pough														

PERSONAL INFORMATION VIAS RESOVED BY NRC. NO COPY OF THIS INFORMATION WAS RETAINED BY THE NRC. TO TOTAL TO

AWS Titan Complaince Matrix

							2014			2015							
	ee Name	Active	Title	2014 User	2014 Job	2014 Annual	2014 Radiation	RSO	RSO	2015 User		2014 Annual	2014 Radiation	RSO	RSO		
First Name	Last Name			List	Usuage	Audit	Sofety Training	Training	Refresher	List	Usuage	Audit	Safety Training	Training	Refresher		
Timothy	Rearick		Ops. Mgr.				4.										
Randall	Reddinger		Skill Labor														
Aaron	Renwick		Ops. Supv.														
Stanley	Riggle																
Todd	Riggle		Ops. Supv.														
Brandon	Rosenberger			27.0			, k										
Larry	Ross							· · · · · · · · · · · · · · · · · · ·									
Kevin	Rupert		Ops. Supv.														
Rod	Seita		Operator														
Evan	Sharrer		Operator														
Joshua	Simmons		Operator					5 m									
Terry	Streightif																
Angela	Swartz		Administrative	14 P													
Larry	Swartz							1277 17									
Aaron	Thomas		Ops. Supv.														
Steven	Townsend		Ops, Supv.														
Robert	Weiss		Ops. Supv.														
Randall	Williams	74	Operator								1						
James	Woodside		Operator														
Jared	Woodside		Operator								L						

Legend

Within Requiremnts
Outside of Requirements

PERSONAL INFORMATION WAS REMOVED
VAS RETAINED BY THE NRC.

PERSONAL INFORMATION WAS REMOVED BY NRC. NO COPY OF THIS INFORMATION WAS RETAINED BY THE NRC.

COMPLIANCE INSPECTION





AWS Inc.

ANNUAL RADIATION SAFETY AUDIT May 2014

LICENSE REVIEW:

U.S. Nuclear Regulatory Commission License No. 37-23410-01

Amendment No. 11 - February 9, 2009

Expiration Date: July 31, 2014

PA Department of Environmental Protection License No. PA-1032

Amendment No. 2 - February 9, 2009

Expiration Date: July 31, 2014

PA Department of Environmental Protection Certification No. PA-G0119

Amendment New - May 27, 2009

Renewal Date: June 30, 2010 - Discontinued

NY Department of Health License No. C3250

Amendment No.3 - May r, 2011

Expiration Date: November 30, 2013 - Will Discontinue

Ohio Department of Health Bureau of Radiation Protection 2010 RECIPROCITY AUTHORIZATION 00004 PA 1011 January 1 through December 31,2010 - Discontinued

PREVIOUS AUDITS:

All items were completed

INSPECTIONS:

- U.S. Nuclear Regulatory Commission November 28, 2007
 No violations identified previous violation(s) closed.
- NY Department of Health January, 2008

 No items of noncompliance were found.
- PA DEP Bureau of Radiation June, 2009
 No items of noncompliance were found.
- OHIO Department of Health Bureau of Radiation Protection-March 2010 No Items of noncompliance were found.
- Pa DEP Bureau of Radiation September 21, 2011 by Celia Rajkovich Recommendations:
 Ensure that gauges are mounted and posted in a manner that ensures ALARA
 Ensure that gauges are properly labeled and marked for transportation

Recommendations were followed and a binder was made up for each Vehicle which include shipping papers, leak tests, NRC & PA DEP licenses

- U.S. Nuclear Regulatory Commission- January, 2011
 No items of noncompliance were found.
- PA DEP Bureau of Radiation May 2012 by Celia Rajkovich
 Labels to be laminated and attached to densometers on trucks.
 Shutters are closed and locked in storage during transporting.
- U.S. Nuclear Regulatory Commission- March, 2014 by Scott Wilson The following items of noncompliance were found:
 - 1: Failure to maintain lögging supervisor and assistant training records
 - 2: Failure to provide safety reviews annually for logging supervisors and assistants
 - 3: Failure to conduct annual unannounced inspections of all logging supervisors

LICENSED MATERIAL SECURITY:

Quantities of Concern requirements completed.

OPERATING PROCEDURES:

Current and in-place.

EMERGENCY PROCEDURES:

Current and in-place.

RADIATION GENERATING DEVICES:

None possessed.

INVENTORY OF SPECIFICALLY LICENSED MATERIALS:

See attached physical inventory.

GENERALLY LICENSED DEVICES:

See attached list of devices.

RADIATION SURVEYS OF RESTRICTED AREAS:

Surveys completed for transport vehicles and logging tools.

RADIATION SURVEY METERS:

See attached calibration documentation.

LEAK TESTING:

Leak testing completed every six months. See attached leak test documentation.

PERSONNEL MONITORING PROGRAM:

Quarterly exposure records are reviewed by badged workers with any exposure during the quarter. Records are signed and placed in the files.

Annual exposure records are not currently provided for badged workers. A request for individual reports has been sent to RADETCO.

The badged worker group is reviewed on a quarterly basis to identify those personnel that are assigned duties that include working with radioactive sources.

ANNUAL REVIEW OF AUTHORIZED USERS:

Last reviews dated 2013.

DISPOSAL OF RADIOACTIVE MATERIALS:

No disposal of licensed material has taken place since last annual review.

SHIPPING OF RADIOACTIVE MATERIALS:

Shipping papers revised to comply with U.S. Department of Transportation requirements.

FACILITY INSPECTION OF RADIOGRAPHY AREAS:

Required signs and postings noted. Security in place for radioactive materials.

FINDINGS:


The review of the Titan Wireline Services Radiation Safety Program was conducted by Vance Byram, RSO, on May 2, 2014. The overall assessment of Radiation Safety at Appalachian Well Services is satisfactory.

The findings and recommendations as identified by this review will be addressed in a timely manner.

Corrective Actions:

- 14 01: Have logging supervisors and assistants attend RSO training, Two of the supervisors and assistants have taken the RSO on May 15, 2014 with the others to be enrolled in the fall class. Radiation Safety training to all other employees to be conducted on an annual basis; in process.
- 14- 02: Conduct unannounced inspections of logging supervisors on job locations; in process
- 14 03: Conduct annual training on timely basis by using an electronic calendar reminder and a training matrix.

RADIOLOGICAL TRAINING CERTIFICATES



CERTIFICATE OF RADIOLOGICAL TRAINING

This is to certify that

Mark Boyer

has successfully completed

24 HOUR RADIATION SAFETY OFFICER TRAINING COURSE AND INSTRUCTION AS REQUIRED BY NUREG-1556 **VOLUME 14 AND 49 CFR 172, SUBPART H**


> presented by Applied Health Physics, LLC May 13th through May 15th, 2014

Todd Y. Mobley, Director, Pechnical Services


Manadément Review

Date

DOT Subpart IT Expiration Date



BY NRC. NO COPY OF THIS INFORMATION WAS RETAINED BY THE NRC



CERTIFICATE OF RADIOLOGICAL TRAINING

This is to certify that

Todd Riggle

has successfully completed

24 HOUR RADIATION SAFETY OFFICER TRAINING COURSE AND INSTRUCTION AS REQUIRED BY NUREG-1556 VOLUME 14 AND 49 CFR 172, SUBPART H

> presented by Applied Health Physics, LLC May 13th through May 15th, 2014

Todd Y. Mobley, Director, Technical Services

Date

DOT Subpart H. Expiration Date