NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL. (TEMPORARY FORM)

. .

CONTROL NO: 1207

FILE:

FROM: Carolina Pwr & Light Co Raleigh, NC		2-5-76	2-7-	DATE REC'D 2-7-76		IWX	RPT		
TO.	E-E-Utley-	·	ORIG		OTHER	<u> </u>	ALC MOO		
10.		· ·	- Unid		UINER	55	NERRO	PDR	XX
]	Mr Reid	· · · · · · · · · · · · · · · · · · ·	one signed		·.	SE	NELO	CALPDI	<u> </u>
CLASS	UNCLASS	PROP INFC) INPUT	NO C	YS REC'D	DC	DCKET	NO:	
	XXX			4	1	50	-201		
DESCRI	PTION:			ENCL	OSURES:	· #			
Ltr re	our 5-30-75	itrtrans	the following:	Info Chec	rmation r k MSIV"S.	egardi with eaks a	ng into regare	egrity (d to po ted with	of swin stulate dynar
•		的法律的		load	s(40	cys e	ncl re	c'd)	ir aynai
	· ·					-		· · ·	
PLANT	VAME: Rot	inson #2				•	. ,	· . :	
S.	AFETY		FOR ACTION	/INFC RI	MATION	F	NV1RO	2-9-7	6 eh:
ASSIGNED AD				AS	SIGNED BR	RANCH C	HIEF		
BRANCH	CHIEF R	end (5)	PR	OJECT MAN	NAGER			
	`	- · ·							
PROJECT	r MANAGER_	Bridges		Ll	C ASST			h	1/ AC
PROJECT	r manager_	Bridges	W/ / CYS ACRS	L1	C ASST	·		k	1/ AC
PROJECT	r manager_ 5st. Ing	Bridges Fram	W/ / Cys Acrs	DISTRIB	C ASST			ĥ	7/ AC
PROJECT LIC. AS FILES	r MANAGER	Bridges	_W/ CYS ACRS INTERNAL D Y PLANT SYSTEM	L1 DISTRIB	C ASST UTION SITE SA	AFETY &	ENVIR		/ AC
PROJECT LIC. AS FILES FDR	I MANAGER_	Bridges	W/ CYS ACRS INTERNAL D Y PLANT SYSTEM TEDESCO	L1 DISTRIB	C ASST UTION SITE SA DENTON	FETY &	ENVIR	.O ANALY	7/ AC
PROJECT LIC. AS FILES FDR	r MANAGER SST	Bridges Frem SYSTEMS SAFET HE INEMAN SCHROEDER	W/ CYS ACRS INTERNAL D Y PLANT SYSTEN TEDESCO BENAROYA	L1 DISTRIB	C ASST UTION SITE SA DENTON	AFETY &	ENVIR MULLE	O ANALY	/ AC
PROJECT LIC. AS FILES FDR SICK/ST/	F MANAGER SST. Ing SST. Ing AFF	Bridges Frem Systems safet HEINEMAN SCHROEDER	W/ CYS ACRS INTERNAL D Y PLANT SYSTEM TEDESCO BENAROYA LAINAS	DISTRIB	C ASST UTION SITE SA DENTON ENVIRO	AFETY &	ENVIR MULLE SIT	O ANALY R. E ANALY	7/ AC
PROJECT LIC. AS FILES FDR SICK/ST/ (2)	I MANAGER_ SST. Ing SST. Ing AFF	Bridges Frem Systems safet HEINEMAN SCHROEDER	W/ CYS ACRS INTERNAL D Y PLANT SYSTEN TEDESCO BENAROYA LAINAS IPPOLITO	DISTRIB 15	C ASST UTION SITE SA DENTON ENVIRO ERNST	AFETY & TECH.	ENVIR MULLE SIT VOL	NO ANALY R. E ANALY LMER	7/ AC
PROJECT LIC. AS FILES FDR SICK/ST/ (2)	I MANAGER_ SST. Ing AFF	Bridges Fram Systems safet HEINEMAN SCHROEDER ENGINEERING MACCARY	W/ CYS ACRS INTERNAL D Y PLANT SYSTEM TEDESCO BENAROYA LAINAS IPPOLITO	L1 DISTRIB	C ASST UTION SITE SA DENTON ENVIRO ERNST BALLARD	AFETY & TECH.	ENVIR MULLE SIT VOL BUN	NO ANALY R. E ANALY LMER CH	7/ AC
PROJECT LIC. AS FILES PDR D SICK/ST/ (2)	r MANAGER SST. Ing AFF	Bridges Frem Systems safet He INEMAN SCHROEDER CHROEDER MGINEERING MACCARY KNIGHT	W/ CYS ACRS INTERNAL D Y PLANT SYSTEM TEDESCO BENAROYA LAINAS IPPOLITO OPERATING RE	L1 DISTRIB 1S	C ASST. UTION SITE SA DENTON ENVIRO ERNST BALLARD SPANGLE	AFETY & TECH.	ENVIR MULLE SIT VOL BUN J.	O ANALY R. E ANALY LMER CH COLLINS	// AC
PROJECT LIC. AS FILES PDR SICK/ST/ (2) C	r MANAGER_ SST. In SST. In SAFF	Budges Budges Systems safet EINEMAN SCHROEDER INGINEERING MACCARY SIL	W/ CYS ACRS INTERNAL D Y FLANT SYSTEM TEDESCO BENAROYA LAINAS IPPOLITO OPERATING RE STELLO	L1 DISTRIB 1S	C ASST UTION SITE SA DENTON ENVIRO ERNST BALLARD SPANGLE	AFETY & TECH.	ENVIR MULLE SIT VOL BUN J. KRE	E ANALY R. E ANALY LMER CH COLLINS CER	// AC
PROJECT LIC. AS FILES FDR SICK/ST/ (2)	I MANAGER_ SST. Ing AFF <u>HAGEMENT</u> F	Budges Budges Systems safet HEINEMAN SCHROEDER MACCARY NIGHT SIHWEIL YAWLICKI	W/ CYS ACRS INTERNAL D Y PLANT SYSTEM TEDESCO BENAROYA LAINAS IPPOLITO OPERATING RE STELLO	L1 DISTRIB 15	C ASST UTION SITE SA DENTON ENVIRO ERNST BALLARD SPANGLE SITE TE	TECH. R CH.	ENVIR MULLE SIT VOL BUN J. KRE	<u>AO ANALY</u> R E ANALY LMER COLLINS CER	7/ AC
PROJECT LIC. AS FILES FDR SICK/ST/ (2) COLLINS	I MANAGER_ SST. Ing AFF <u>HAGEMENT</u> F	Budges Systems safet EINEMAN SCHROEDER MGINEERING MACCARY CNIGHT SIHWEIL AWLICKI	W/ CYS ACRS INTERNAL D Y PLANT SYSTEM TEDESCO BENAROYA LAINAS IPPOLITO OPERATING RE STELLO OPERATING TE	L1 DISTRIB 1S EACTORS	C ASST UTION SITE SA DENTON ENVIRO ERNST BALLARD SPANGLE SITE TE GAMMILL	TECH. R CH.	ENVIR MULLE SIT VOL BUN J. KRE AT&	O ANALY R. E ANALY LMER COLLINS GER	// AC
PROJECT LIC. AS FILES FDR SICK/ST/ (2) COLLINS STON	F MANAGER_ SST. In SST. In SAFF AFF <u>HAGEMENT</u> F	Budges Budges Systems safet REINEMAN SCHROEDER MGINEERING MACCARY SNIGHT SIHWEIL PAWLICKI EACTOR SAFET	W/ CYS ACRS INTERNAL D Y FLANT SYSTEM TEDESCO BENAROYA LAINAS IPPOLITO OPERATING RE STELLO OPERATING TE EISENHUT	L1 DISTRIB 15 EACTORS	C ASST. UTION SITE SA DENTON ENVIRO ERNST BALLARD SPANGLE SITE TE GAMMILL STEPP	AFETY & TECH. R CH.	ENVIR MULLE SIT VOL BUN J. KRE <u>AT&</u> SAL	O ANALY R. E ANALY LMER CH COLLINS GER I TZMÀN	// AC
PROJECT LIC. AS FILES FDR SICK/ST/ (2) C LECT MAN COLLINS STON RSON	F MANAGER_ SST. In AFF <u>AFF</u> <u>NAGEMENT</u> F R	Budges Budges Systems safet EINEMAN SCHROEDER MGINEERING MACCARY SIGHT SIHWEIL PAWLICKI EACTOR SAFET OSS	W/ CYS ACRS INTERNAL D Y FLANT SYSTEM TEDESCO BENAROYA LAINAS IPPOLITO OPERATING RE STELLO Y EISENHUT SHAO	L1 DISTRIB 1S EACTORS	C ASST. UTION SITE SA DENTON ENVIRO ERNST BALLARD SPANGLE SITE TE GAMMILL STEPP HULMAN	TECH. R CH.	ENVIR MULLE SIT VOL BUN J. KRE <u>AT&</u> SAL RUT	O ANALY R. E ANALY LMER COLLINS CER I TZMAN BERG	// AC
PROJECT LIC. AS FILES FDR SICK/ST/ (2) C LECT MAN COLLINS STON CRSON	F MANAGER SST. In SST. In SAFF AFF NAGEMENT F R R N	Budges Budges Systems safet EINEMAN SCHROEDER MGINEERING MACCARY CNIGHT SINWEIL PAWLICKI EACTOR SAFET COSS IOVAK	W/ CYS ACRS INTERNAL D Y FLANT SYSTEM TEDESCO BENAROYA LAINAS IPPOLITO OPERATING RE STELLO OPERATING TE EISENHUT SHAO BAER	L1 DISTRIB 1S CACTORS	C ASST UTION SITE SA DENTON ENVIRO ERNST BALLARD SPANGLE SITE TE GANMILL STEPP HULMAN	TECH. R CH.	ENVIR MULLE SIT VOL BUN J. KRE AT& SAL RUT	<u>AO ANALY</u> R <u>E ANALY</u> LMER COLLINS CER I TZMÀN BERG	7/ AC
PROJECT LIC. AS FILES FDR SICK/ST/ (2) COLLINS STON COLLINS STON CRSON Z EMES	I MANAGER_ SST. Ing AFF <u>HAGEMENT</u> F R R R R R	Budges Budges Systems safet EINEMAN SCHROEDER CHROEDER CHROEDER CHROEDER SIGINEERING MACCARY KNIGHT SIHWEIL AWLICKI EACTOR SAFET OSS OVAK OSETOCZY	W/ CYS ACRS INTERNAL D Y PLANT SYSTEM TEDESCO BENAROYA LAINAS IPPOLITO OPERATING RE STELLO OPERATING TE EISENHUT SHAO BAER SCHWENCER	L1 DISTRIB 1S EACTORS	C ASST. UTION SITE SA DENTON ENVIRO ERNST BALLARD SPANGLE SITE TE GAMMILL STEPP HULMAN	TECH. R CH.	ENVIR MULLE SIT VOL BUN J. KRE <u>AT&</u> SAL RUT	O ANALY R. E ANALY LMER COLLINS GER I TZMÀN BERG	7/ AC
PROJECT LIC. AS FILES FDR D SICK/ST/ (2) C LECT MAN COLLINS STON RSON Z 'EMES	F MANAGER_ SST. In AFF <u>AFF</u> <u>HAGEMENT</u> F R R R R R C	Budges Budges Systems safet EINEMAN SCHROEDER CHROE	W/ CYS ACRS INTERNAL D Y FLANT SYSTEM TEDESCO BENAROYA LAINAS IPPOLITO OPERATING RE STELLO OPERATING TE EISENHUT SHAO BAER SCHWENCER GRIMES	L1 DISTRIB 1S EACTORS	C ASST. UTION SITE SA DENTON ENVIRO ERNST BALLARD SPANGLE SITE TE GAMMILL STEPP HULMAN	TECH. R CH. ISCELL	ENVIR MULLE SIT VOI BUN J. KRE <u>AT&</u> SAL RUT	O ANALY R. E ANALY LMER COLLINS GER I TZMÀN BERG	1/ AC
PROJECT LIC. AS FILES FDR D SICK/ST/ (2) C LECT MAN COLLINS STON CRSON Z 'EMES	F MANAGER_ SST. In AFF <u>AFF</u> <u>AAGEMENT</u> F R R R R R C	Budges Budges Systems safet EINEMAN SCHROEDER CHROE	W/ CYS ACRS INTERNAL D Y FLANT SYSTEM TEDESCO BENAROYA LAINAS IPPOLITO OPERATING RE STELLO OPERATING TE SHAO BAER SCHWENCER GRIMES EXTERNAL D	L1 DISTRIB 1S EACTORS CCIL	C ASST. UTION SITE SA DENTON ENVIRO ERNST BALLARD SPANGLE SITE TE GAMMILL STEPP HULMAN <u>M</u>	TECH. R CH. ISCELL	ENVIR MULLE SIT VOI BUN J. KRE <u>AT&</u> SAL RUT	O ANALY R. E ANALY LMER COLLINS GER I TZMÀN BERG	1/ AC
PROJECT LIC. AS FILES FDR D SICK/ST/ (2) C LECT MAN COLLINS STON CRSON C COLLINS STON CRSON C Z 'EMES	r MANAGER_ SST. In SST. In SST. In SAFF AFF HAGEMENT F R R R R R R C C Hactsur	Budges Systems safet EINEMAN SCHROEDER CHR	W/ CYS ACRS INTERNAL D Y FLANT SYSTEM TEDESCO BENAROYA LAINAS IPPOLITO OPERATING RE STELLO OPERATING TE STELLO OPERATING TE STELLO COPERATING TE S	L1 DISTRIB 1S EACTORS CCIL	C ASST. UTION SITE SA DENTON ENVIRO ERNST BALLARD SPANGLE SITE TE GAMMILL STEPR HULMAN M UTION	TECH. R CH. S	ENVIR MULLE SIT VOI BUN J. KRE <u>AT&</u> SAL RUT ANEOUS BROO:	O ANALY R. E ANALY LMER COLLINS GER I TZMÀN BERG	// AC
PROJECT LIC. AS FILES FDR SICK/ST/ (2) C UECT MAN COLLINS STON CRSON Z EMES AL PDR	r MANAGER SST. Ing AFF AFF <u>AAGEMENT</u> F R N R C Mactsur	Budges Systems safet EINEMAN SCHROEDER INGINEERING ACCARY NIGHT SHWEIL AWLICKI EACTOR SAFET OSS IOVAK OSETOCZY HECK	W/ CYS ACRS INTERNAL D Y PLANT SYSTEM TEDESCO BENAROYA LAINAS IPPOLITO OPERATING RE STELLO OPERATING TE Y EISENHUT SHAO BAER SCHWENCER GRIMES EXTEGNAL D NATIONAL LAB REGION V-1&E-(V	L1 DISTRIB 1S ACTORS CIL.	C ASST. UTION SITE SA DENTON ENVIRO ERNST BALLARD SPANGLE SITE TE GAMMILL STEPP HULMAN M UTION W/ CYS CREEK)	TECH. R CH. S	ENVIR MULLE SIT VOL BUN J. KRE AT& SAL RUT ANEOUS BROO: ULRII	O ANALY R. E ANALY LMER COLLINS GER I TZMÀN BERG KHAVEN I (SON (OI	// AC (SIS (SIS (SIS) (S
PROJECT LIC. AS FILES FDR COLLINS COLLINS STON CRSON Z 'EMES AL PDR	F MANAGER SST. Ing AFF NAGEMENT F NAGEMENT F N R C Ma. Isui	Budges Systems safet EINEMAN SCHROEDER MGINEERING MACCARY NIGHT SHWEIL AWLICKI EACTOR SAFET OSS IOVAK OSETOCZY HECK	W/ CYS ACRS INTERNAL D Y PLANT SYSTEM TEDESCO BENAROYA LAINAS IPPOLITO OPERATING RE STELLO OPERATING TE Y EISENHUT SHAO BAER SCHWENCER GRIMES EXTEGNAL D NATIONAL LAB REGION V-1&E-(Y LA PDR CONSULTANCE	L1 DISTRIB IS SACTORS CIL.	C ASST UTION SITE SA DENTON ERNST BALLARD SPANGLE SITE TE GAMMILL STEPP HULMAN M UTION CYS CREEK)	TECH. TECH. R CH. S	ENVIR MULLE SIT VOL BUN J. KRE AT& SAL RUT ANEOUS BROO: ULRIN	O ANALY R. E ANALY IMER COLLINS GER I TZMÀN BERG KHAVEN I (OI	// AC <u>(SIS</u> <u>(SIS</u> <u>(SIS</u>) <u>(SIS</u>)





Carolina Power & Light Company

February 5, 1976

File: NG-3514 (R)

Serial: NG-76-155

Director of Nuclear Reactor Regulation Attention: Mr. Robert W. Reid, Chief Operating Reactors Branch No. 4 U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Dear Mr. Reid:



H. B. ROBINSON UNIT NO. 2 DOCKET NO. 50-261 LICENSE NO. DPR-23 INTEGRITY OF SWING-CHECK MSIV'S

Your letter of May 30, 1975, requested information concerning the integrity of the H. B. Robinson Unit No. 2 main steam isolation valves under the dynamic loads associated with postulated steam line breaks. Our letters NG-75-1100 of July 16, 1975, and NG-75-1772 of October 31, 1975, progressively reported the status of our investigations. The evaluation of the Robinson main steam isolation valves and main steam line check valves is now complete and the information requested is provided in an Attachment to this letter.

Analyses have been performed using the "worst case" approach. The trip valve analysis assumed a double-ended pipe break at the check valve outlet. The check valve analysis assumed a similar break at the trip valve inlet. Any other postulated pipe break would be further from the valves and would therefore result in a lower disc velocity and impact energy. The analyses also considered the use of the various steam pressures and steam flows which would be representative of different power levels. A power level of about 53% was finally used in the analyses because it yielded the most conservative results. In all cases, the values assumed for material physical properties were the most limiting. The actual physical properties can be expected to be less limiting.

Both pre-impact and post-impact analyses were performed.

Pre-Impact

The pre-impact analysis considered the centrifugal forces acting on the tail link and rockshaft. It was found that these forces cause the tail link and rockshaft to deflect in the radial direction. In addition,



336 Fayetteville Street • P. O. Box 1551 • Raleigh, N. C. 27602

Mr. Robert W. Reid

February 5, 1976

there will be sufficient radial deflection to permit the valve disc to contact the valve body just before the disc impacts with the valve seat. Calculations indicate that the disc will rebound slightly after contact with the body and continue on to impact the seat and effect valve closure. Evaluation of the pre-impact analysis indicates that this contact between the valve disc and valve body does not result in loss of function of the disc or body.

Post-Impact

The post-impact analysis conservatively assumed that no energy loss occurs during pre-impact contact between the valve disc and valve body even though such contact can be expected to result in some loss of disc energy. The analysis dealt primarily with the forces and strains generated in the disc, seat, and tail link hub by the impact of the disc on the seat. The post-impact strains occurring in the valve are all less than the minimum ultimate strain capacity for the respective materials involved. The effect on the valve is that the disc and seat will undergo some plastic deformation in the impact areas but will still close to effectively shut off steam flow.

To provide an increased margin of safety, modifications as described in the Attachment are planned for the valves. The modifications are similar to those made on the St. Lucie Unit No. 1 Plant for Florida Power and Light Company. With the modifications, the potential deflection in the rockshaft and tail link is reduced to .25 in. The maximum tail link strain occurs in the tail link hub and is less than 20% of the minimum ultimate strain capacity of the material. The strains in the modified disc and seat are greatly reduced with the maximum strain occurring in an element of the check valve disc. The maximum strain in the check valve is 60% of the strain capacity of the disc material. Also, the use of a larger operating air cylinder will greatly reduce the strains in the air operated trip valve because the velocity of the trip valve disc will be significantly reduced.

A cyclic fatigue analysis of the modified valve internals has been performed and has demonstrated that a satisfactory number of spurious closures during 100% power operation can be accommodated. The modified valves have been found to be satisfactory under all conditions analyzed and will provide a significantly increased performance margin.

Yours very truly,

Vice-President Bulk Power Supply

DBW:mvp

Attachment

1. Analysis

- a) Impact energy for postulated double ended rupture of the main steam piping - The maximum calculated impact energy is absorbed by the disc and seat of the check valve and is equal to 3.32 x 10⁶ in-1bs. The maximum calculated impact energy absorbed by the disc and seat of the air operated trip valve is 2.34 x 10⁶ in-1bs.
- b) <u>Methods used in the dynamic analysis</u> The methods used in the dynamic analysis are the same as those described in the analysis for St. Lucie Unit No. 1 which was submitted to the NRC in the St. Lucie FSAR.

c) Summary of the maximum calculated strains

Location	Calculated Generalized Strain	Ultimate Strain Capacity
Stainless Steel Seat Cladding	20.5%	40%
Carbon Steel Seat Body	19.7%	23%
Stainless Steel Disc Cladding	15.2%	40%
Carbon Steel Disc Body	16.0%	23%

2. Modifications Planned

The following modifications will be made to both the trip valve and the check valve.

- a) The rockshaft will be replaced with a rockshaft of larger diameter (2.162 in. vs. 1.625 in.) and of different material with stronger physical properties. A larger diameter bushing will also be added.
- b) The tail link will be reinforced to improve its resistance to bending in the hub area (Figures 1 and 2). This is accomplished by adding material to the section between the tail link sleeve and tail link hub as well as increasing the length of the hub.
- c) A stainless steel seat ring will be welded to the existing valve seat (Figure 3).
- d) The disc will have an increased stainless steel weld overlay added to the area that impacts the valve seat upon closure. The disc will be recessed and tapered to allow the tail link hub to penetrate the disc (Figure 4).

In addition to the above, the operating cylinder for the trip valve will be replaced with a larger diameter (14.0 in.) cylinder with a design pressure of 1000 psig.

3. Schedule

We are presently in the process of finalizing manufacturing drawings for the modified valve internals. The drawings are scheduled to be completed by the first week of February. Pending procurement of materials, we are planning to complete the modifications on the Robinson valves during the fall refueling outage this year.



Figure 1. Modified Tail Link-Side View





-3,





Figure 4. Modified Disc

.