IBUTION FOR PART 50 DOCKET MAT (TEMPORARY FORM)

5091 CONTROL NO:

						FILE:					
FROM: Carolina Power & Light Company Raleigh, N. C. 27602			DATE OF DOC	DATE	REC'D	LTR	MEMO	RPT	OTHER		
E. E. Utley		6-22-73	6-28-73.		Х	j .					
TO:			ORIG	CC	OTHER		SENT AEC PDR X				
]	Mr. O'Leary		3 signed			1	SENT	LOCAL P	DR <u>X</u>		
CLASS	UNCLASS	PROP INFO	INPUT	NO CY	CYS REC'D DOCKET			r NO:	NO:		
	х			40		50-261					
DESCRI	PTION:			FNCT	OSTIDES.				· · · · · · · · · · · · · · · · · · ·		

Ltr re their 7-6-71 ltr.....furnishing info re pressurizer safety valve nozzles.....

Do Not Remove

ACKNOWLEDGED

PLANT NAME: H. B. Robinson Unit No. 2

BUTLER(L)	SCHWENCER(L)	ZIEMANN(L)	REGAN(E)		
W/ Copies	W/ Copies	W/ Copies	W/ Copies		•
CLARK(L)	STOLZ(L)	DICKER(E)	· -	·	
W/ Copies	W/ Copies	W/ Copies	W/ Copies		
GOLLER(L)	VASSALLO(L)	KNIGHTON (E)			•
W/ Copies	W/ Copies	W/ Copies	W/ Copies		•
KNIEL(L)	SCHEMEL(L)	YOUNGBLOOD (E)		•	
W/ Copies	W/9 Copies	W/ Copies	W/ Copies		
		INTERNAL DISTRIBU	TION		
REG FILE	TECH REVIEW	DENTON	LIC ASST	A/T IND	
AEC-PDR	HENDRIE	GRIMES	BROWN (E)	BRAITMAN	
OGC, ROOM P-506A	A SCHROEDER	GAMMILL	DIGGS (L)	SALTZMAN	
MUNTZING/STAFF	MACCARY	KASTNER	GEARIN (L)		
CASE	KNIGHT	BALLARD	GOULBOURNE (E)	PLANS	
GIAMBUSSO	PAWLICKI	SPANGLER	LEE (L)	MCDONALD	ı
BOYD	SHAO		MAIGRET (L)	DUBE	
MOORE (L)(BWR)	STELLO	ENVIRO	SERVICE (L)		
DEYOUNG(L)(PWR)	HOUSTON	MULLER	SHEPPARD (E)	INFO	•
SKOVHOLT (L)	NOVAK	DICKER	SMITH (L)	C. MILES	
P. COLLINS	ROSS	KNIGHTON	TEETS (L)	•	
	IPPOLITO	YOUNGBLOOD	WADE (E)		
REG OPR	TEDESCO	REGAN	WILLIAMS (E)		
FILE & REGION(3)	LONG	PROJECT LDR	WILSON (L)		•
MORRIS	LAINAS	·	` '		•
STEELE	BENAROYA	HARLESS	•	•	+9)
	VOLLMER				17.
		EXTERNAL DISTRIBU	TION		
1 - LOCAL PDR	Hartville, S. (3.	.,		dis

FOR ACTION/INFORMATION

1 - DTIE (ABERNATHY)

(1)(2)(9)-NATIONAL LAB'S

1 - NSIC (BUCHANAN)

1-R. CARROLL-OC, GT-B227

1 - ASLB(YORE/SAYRE/

1-R. CATLIN, E-256-GT

WOODARD/"H" ST.

1-CONSULTANT'S

16 - CYS ACRS HOLDING SENT TO LIC ASST.

NEWMARK/BLUME/AGBABIAN

S. TEETS ON 6-29-73 1-GERALD ULRIKSON...ORNL

1-PDR-SAN/LA/NY 1-GERALD LELLOUCHE BROOKHAVEN NAT. LAB 1-AGMED (WALTER KOESTER

RM-C-427-GT 1-RD..MULLER..F-309 GT



Carolina Power & Light Company

June 22, 1973

FILE: 5213

NG-73-118

Mr. John F. O'Leary, Director Directorate of Licensing U. S. Atomic Energy Commission Washington, D. C. 20545

Dear Mr. O'Leary:

H. B. ROBINSON UNIT NO. 2 LICENSE DPR-23 PRESSURIZER SAFETY VALVE NOZZLES



In our letter of July 6, 1971, to Dr. Peter A. Morris we stated that we would perform a liquid penetrant inspection of the pressurizer safety valve nozzles during our first refueling outage. This inspection was to check for possible sensitization of the type 316 stainless steel nozzle due to the hard surfacing operation during manufacture. Visual and liquid penetrant inspections were performed during our recent first refueling outage. No indication of sensitization was found, and the valves were returned to service. Normal inservice inspection will continue to be performed on these valves in accordance with ASME-Section XI, Inservice Inspection of Nuclear Reactor Coolant Systems.

Very truly yours,

E. E. Utley Vice-President

Bulk Power Supply

KEB/DBW/1w

cc: Mr. C. D. Barham

Mr. N. B. Bessac

Mr. B. J. Furr

Mr. D. V. Menscer

Mr. D. B. Waters

2-0-4-a

