

50-261

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

TO: Mr. Edson G. Case

FROM: CP&L
Raleigh, N. C. 27602
E. E. Utley

DATE OF DOCUMENT
09/09/77

DATE RECEIVED
09/12/77

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

1 SIGNED

DESCRIPTION

ENCLOSURE

Consists of repts detailing the results of examinations of the first containment surveillance tendon sample which was removed in March, 1976 entitled:

1. "Tendon Surveillance Report Review"
2. "inspection of Containment Prestressing Surveillance Tendon form H. B. Robinson Unit No. 2 Plant"
3. "Failure Analysis of a Reinforcing Rod from the Containment Prestressing Surveillance Tendon from H. B. Robinson Unit No. 2 Plant."

jcm 09/16/77

1p

PLANT NAME: H. B ROBINSON UNIT # 2

1" *566 RPTS*

REPRODUCE LTR.

Dist PER R. INGRAM 9/15/77

13 ENCL.

SAFETY

FOR ACTION/INFORMATION

ENVIRONMENTAL

ASSIGNED AD:

ASSIGNED AD: V. MOORE (LTR)

BRANCH CHIEF:

BRANCH CHIEF:

PROJECT MANAGER: **(3)** ZWETZIG

PROJECT MANAGER:

LICENSING ASSISTANT: INGRAM

LICENSING ASSISTANT:

B. HARLESS

INTERNAL DISTRIBUTION

REG FILES

SYSTEMS SAFETY

PLANT SYSTEMS

SITE SAFETY &

NRC PDR

R. MATTSON

TEDESCO

ENVIRON ANALYSIS

T & E (2)

SCHROEDER

BENAROYA

DENTON & MULLER

FIELD

LATNAS

CRITCHFIELD

GOSSICK & STAFF

ENGINEERING

IPPOLITO

HANAUER

KNIGHT

F. ROSA

ENVIRO TECH.

MTPC

BOSNAK

ERNST

CASE

SIHWELL

OPERATING REACTORS

BALLARD

BOYD

PAWLICKI

STELLO

YOUNGBLOOD

EISENHUT *LTR.*

PROJECT MANAGEMENT

REACTOR SAFETY

SHAO

SITE TECH.

SKOVHOLT

ROSS

BAER

P. COLLINS

NOVAK

BUTLER *LTR.*

GAMMILL (2)

HOUSTON

ROSZTOCZY

GRIMES

MELTZ

CHECK

SITE ANALYSIS

HELTEMES

VOLLMER

SK

AT&I

BUNCH

SALTZMAN

J. COLLINS

RUTBERG

KREGER

EXTERNAL DISTRIBUTION

CONTROL NUMBER

LPDR: *HARTSVILLE SC*

TIC

NSIC

NAT LAB

REG IV (J. HANCHETT)

~~ACRS~~ SENT CATEGORY **B**

104 ENCL. 16 LTR.S

MISC
2
772590008
B

REGULATORY DOCKET FILE COPY
CP&L

Carolina Power & Light Company

September 9, 1977



FILE: NG 3514 (R)

SERIAL: NG-77-1018

Mr. Edson G. Case, Acting Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555


RE: H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NOS. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
REPORT OF SURVEILLANCE TENDON TEST RESULTS

Dear Mr. Case:

Attached you will find three reports detailing the results of examinations on the first containment surveillance tendon sample which was removed in March 1976. The reports are "Tendon Surveillance Report Review" by the CP&L Power Plant Engineering Section, "Inspection of Containment Prestressing Surveillance Tendon from H. B. Robinson Unit No. 2 Plant" and "Failure Analysis of a Reinforcing Rod from the Containment Prestressing Surveillance Tendon from H. B. Robinson Unit No. 2 Plant" by Battelle Columbus Laboratories.

These reports are submitted in accordance with the reporting requirements given in Regulatory Guide 10.1.

Yours very truly,


E. E. Utley
Senior Vice President
Power Supply

CSB/DLB/gsm
Attachment

336 Fayetteville Street • P. O. Box 1551 • Raleigh, N. C. 27602

772590008