

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION III 2443 WARRENVILLE RD. SUITE 210 LISLE, IL 60532-4352

September 2, 2014

Mr. Raymond Lieb Site Vice President FirstEnergy Nuclear Operating Company Davis-Besse Nuclear Power Station 5501 North State Route 2 Oak Harbor, OH 43449-9760

SUBJECT: MID-CYCLE ASSESSMENT LETTER FOR DAVIS-BESSE NUCLEAR POWER STATION

Dear Mr. Lieb:

On August 5, 2014, the U.S. Nuclear Regulatory Commission (NRC) completed its mid-cycle performance review of Davis-Besse Nuclear Power Station. The NRC reviewed the most recent quarterly performance indicators (PIs) in addition to inspection results and enforcement actions from July 1, 2013 through June 30, 2014. This letter informs you of the NRC's assessment of your facility during this period and its plans for future inspections at your facility.

The NRC determined that overall, Davis-Besse was operated in a manner that preserved public health and safety and met all cornerstone objectives. The NRC determined the performance at Davis-Besse Nuclear Power Station during the most recent quarter was within the Licensee Response Column of the NRC's Reactor Oversight Process (ROP) Action Matrix because all inspection findings had very low (i.e., green) safety significance, and all PIs indicated that your performance was within the nominal, expected range (i.e., green). Therefore, the NRC plans to conduct ROP baseline inspections at your facility.

During the fourth quarter of 2013, of Davis-Besse Nuclear Power Station was within the Regulatory Response Column of the NRC's ROP Action Matrix because of one or more greater-than-green Security Cornerstone inputs described in NRC Inspection Reports 05000346/2012405 and 05000346/2012403 dated November 8, 2012, and September 7, 2012, respectively. In response to these Action Matrix inputs, the NRC informed you that a supplemental inspection would be required. On September 6, 2013, you informed the NRC that the station was ready for the supplemental inspection.

NRC Inspection Report 05000346/2013408, dated December 19, 2013, advised you that the supplemental inspection was satisfactorily completed and that the NRC determined that completed or planned corrective actions were sufficient to address the performance that led to the one or more greater-than-green Security Cornerstone inputs. As a result, the NRC determined that the inputs would be closed and the performance issues would not be

R. Lieb

considered as Action Matrix inputs as of December 19, 2013. Thus, the NRC determined the performance at Davis-Besse Nuclear Power Station was considered to be in the Licensee Response Column of the ROP Action Matrix as of December 19, 2013.

As a result of the Safety Culture Common Language Initiative, the terminology and coding of cross-cutting aspects were revised. All cross-cutting aspects identified during inspections conducted in calendar year 2014 reflect this revision to Inspection Manual Chapter (IMC) 0310. Cross-cutting aspects identified in 2013 using the 2013 terminology were converted to the latest revision in accordance with the cross-reference in IMC 0310 during the mid-cycle assessment review and evaluated for cross-cutting themes and potential substantive cross-cutting issues in accordance with IMC 0305.

The enclosed inspection plan lists the inspections scheduled through December 31, 2015. Routine inspections performed by resident inspectors are not included in the inspection plan. The inspections listed during the last 9 months of the inspection plan are tentative and may be revised at the end-of-cycle performance review. The NRC provides the inspection plan to allow for the resolution of any scheduling conflicts and personnel availability issues. The NRC will contact you as soon as possible to discuss changes to the inspection plan should circumstances warrant any changes. This inspection plan does not include security related inspections, which will be sent via separate, non-publicly available correspondence.

The enclosed plan does include a triennial "Evaluations of Changes, Tests and Experiments and Permanent Plant Modifications" inspection per procedure 71111.17T, triennial "Component Design Basis" inspection per procedure 71111.21, and biennial "Problem Identification and Resolution" inspection per procedure 71152.

In response to the accident at Fukushima, the Commission issued Order EA-12-049, "Order Modifying Licenses with Regard to Requirements for Mitigation Strategies for Beyond-Design-Basis External Events," which requires licensees to develop, implement, and maintain guidance and strategies to maintain or restore core cooling, containment, and spent fuel pool cooling capabilities following a beyond-design-basis external event. Additionally, the Commission issued Order EA-12-051, "Order Modifying Licenses with Regard to Reliable Spent Fuel Pool Instrumentation," which requires licensees to have a reliable means of remotely monitoring wide-range Spent Fuel Pool levels to support effective prioritization of event mitigation and recovery actions in the event of a beyond-design-basis external event. The NRC is conducting audits of licensee efforts towards compliance with these Orders. This audit includes an onsite component in order for the NRC to evaluate licensee plans for complying with the Orders, as described in site-specific submittals, and to receive and review information relative to associated open items. This onsite activity will occur in the months prior to a declaration of compliance for the first unit at each site, and will aid staff in development of an ultimate Safety Evaluation for the site. The date for the onsite component at your site is being coordinated with your staff. A site-specific audit plan for the visit will be provided in advance to allow sufficient time for preparations.

R. Lieb

In accordance with Title 10 of the *Code of Federal Regulations* 2.390, "Public Inspections, Exemptions, Requests for Withholding," of the NRC's "Rules of Practice," a copy of this letter, its enclosure, and your response (if any) will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records System (PARS) component of NRC's Agencywide Documents Access and Management System (ADAMS). ADAMS is accessible from the NRC Web site at <u>http://www.nrc.gov/reading-rm/adams.html</u> (the Public Electronic Reading Room).

Please contact me at 630–829–9833 with any questions you have regarding this letter.

Sincerely,

/RA/

Jamnes L. Cameron, Chief Branch 4 Division of Reactor Projects

Docket No. 50–346 License No. NPF–3

Enclosure: Davis-Besse Nuclear Power Station Inspection/Activity Plan

cc w/encl: Distribution via LISTSERV®

R. Lieb

In accordance with Title 10 of the *Code of Federal Regulations* 2.390, "Public Inspections, Exemptions, Requests for Withholding," of the NRC's "Rules of Practice," a copy of this letter, its enclosure, and your response (if any) will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records System (PARS) component of NRC's Agencywide Documents Access and Management System (ADAMS). ADAMS is accessible from the NRC Web site at <u>http://www.nrc.gov/reading-rm/adams.html</u> (the Public Electronic Reading Room).

Please contact me at 630–829–9833 with any questions you have regarding this letter.

Sincerely,

/**RA**/

Jamnes L. Cameron, Chief Branch 4 Division of Reactor Projects

Docket No. 50–346 License No. NPF–3

Enclosure: Davis-Besse Nuclear Power Station Inspection/Activity Plan

cc w/encl: Distribution via LISTSERV®

| DISTRIBUTION w/encl: | |
|------------------------------|--------------------------------|
| Anthony Bowers | Carole Ariano |
| RidsNrrDorlLpl3-2 Resource | Linda Linn |
| RidsNrrPMDavisBesse Resource | DRPIII |
| RidsNrrDirsIrib Resource | DRSIII |
| Cynthia Pederson | Patricia Buckley |
| Darrell Roberts | Carmen Olteanu |
| Steven Orth | ROPassessment.Resource@nrc.gov |
| Allan Barker | |

DOCUMENT NAME: Davis-Besse 2014 Mid-Cycle Letter

 \square Publicly Available \square Non-Publicly Available \square Sensitive \square Non-Sensitive To receive a copy of this document, indicate in the concurrence box "C" = Copy without attach/encl "E" = Copy with attach/encl "N" = No copy

| OFFICE | RIII | | | | |
|--------|---|----------|--|--|--|
| NAME | BBartlett for JRutkowski <i>:</i> mt | JCameron | | | |
| DATE | 08/21/14 | 08/25/14 | | | |

OFFICIAL RECORD COPY

Page 1 of 2

08/22/2014 09:35:21 Report 22

Davis-Besse Inspection / Activity Plan 09/01/2014 - 12/31/2015

| Unit | t Planned Dates | | | | No. of Staff |
|--------|-----------------|------------|----------------|--|--------------|
| Number | Start | End | Inspection A | ctivity Title | on Site |
| | | | BI MODS | - MODIFICATIONS/50.59 INSPECTION | 3 |
| 1 | 11/03/2014 | 11/21/2014 | IP 7111117T | Evaluations of Changes, Tests, and Experiments and Permanent Plant Modifications | |
| | | | BI RP | - RADIATION PROTECTION BASELINE INSPECTION | 1 |
| 1 | 09/08/2014 | 09/12/2014 | IP 71124.07 | Radiological Environmental Monitoring Program | |
| 1 | 09/08/2014 | 09/12/2014 | IP 71151-BI0 | 1 | |
| 1 | 09/08/2014 | 09/12/2014 | IP 71151-OR | 01 | |
| 1 | 09/08/2014 | 09/12/2014 | IP 71151-PR | 01 | |
| | | | ISFSI | - ISFSI OPERATION AT A REACTOR SITE | 1 |
| 1 | 11/01/2014 | 11/30/2014 | IP 60855.1 | Operation of an Independent Spent Fuel Storage Installation at Operating Plants | |
| | | | BI RP | - RADIATION PROTECTION BASELINE INSPECTION | 1 |
| 1 | 12/01/2014 | 12/05/2014 | IP 71124.05 | Radiation Monitoring Instrumentation | |
| | | | BI OLRQ | - BIENNIAL REQUAL PROGRAM INSPECTION | 2 |
| 1 | 12/08/2014 | 12/12/2014 | IP 7111111B | Licensed Operator Requalification Program | |
| | | | BI ENG | - COMPONENT DESIGN BASIS INSPECTION | 6 |
| 1 | 01/26/2015 | 02/27/2015 | IP 7111121 | Component Design Bases Inspection | |
| | | | BI EPX | - EP EXERCISE INSPECTION / PI VERIFICATION | 2 |
| 1 | 05/04/2015 | 05/08/2015 | IP 7111407 | Exercise Evaluation - Hostile Action (HA) Event | |
| 1 | 05/04/2015 | 05/08/2015 | IP 71151 | Performance Indicator Verification | |
| | | | BI RP | - RADIATION PROTECTION BASELINE INSPECTION | 1 |
| 1 | 02/23/2015 | 02/27/2015 | IP 71124.06 | Radioactive Gaseous and Liquid Effluent Treatment | |
| | | | 71152B | - BIENNIAL PI&R | 4 |
| 1 | 03/23/2015 | 04/10/2015 | IP 71152B | Problem Identification and Resolution | |
| | | | BI RP | - RADIATION PROTECTION BASELINE INSPECTION | 1 |
| 1 | 04/20/2015 | 04/24/2015 | IP 71124.03 | In-Plant Airborne Radioactivity Control and Mitigation | |
| 1 | 04/20/2015 | 04/24/2015 | IP 71124.04 | Occupational Dose Assessment | |
| | | | BI RP | - RADIATION PROTECTION BASELINE INSPECTION | 1 |
| 1 | 05/04/2015 | 05/08/2015 | IP 71124.02 | Occupational ALARA Planning and Controls | |
| 1 | 05/04/2015 | 05/08/2015 | IP 71151-BI0 | 1 | |
| 1 | 05/04/2015 | 05/08/2015 | IP 71151-OR | 01 | |
| 1 | 05/04/2015 | 05/08/2015 | IP 71151-PR | 01 | |
| | | | OL PREP | - INIT EXAM/JUNE 2015 | 2 |
| 1 | 05/18/2015 | 05/22/2015 | W90327 | OL - INITIAL EXAM - 2015 JUN-JUL - DAVIS-BESSE | |
| | | | | | |

This report does not include INPO and OUTAGE activities. This report shows only on-site and announced inspection procedures. Page 2 of 2

08/22/2014 09:35:21 Report 22

Davis-Besse Inspection / Activity Plan 09/01/2014 - 12/31/2015

| Unit Number | | d Dates End | Inspection A | ctivity | Title | No. of Staff on Site |
|----------------|------------|----------------|--------------|-----------|--|-------------------------|
| | | | OL EXAM | - INIT EX | AM/JUNE 2015 | 3 |
| 1 | 06/15/2015 | 06/26/2015 | W90327 | | OL - INITIAL EXAM - 2015 JUN-JUL - DAVIS-BESSE | |
| | | | BI RP | - RADIAT | ION PROTECTION BASELINE INSPECTION | 1 |
| 1 | 11/02/2015 | 11/06/2015 | IP 71124.01 | | Radiological Hazard Assessment and Exposure Controls | |
| 1 | 11/02/2015 | 11/06/2015 | IP 71124.02 | | Occupational ALARA Planning and Controls | |

This report does not include INPO and OUTAGE activities. This report shows only on-site and announced inspection procedures.