

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

<p>1. LICENSEE/LOCATION INSPECTED: Engineering Associates P.O. Box 1900 Cody, Wyoming 82414 Location; 902 13<sup>th</sup> Street, Cody, WY REPORT NO: 2014-001</p>	<p>2. NRC/REGIONAL OFFICE  U.S. Nuclear Regulatory Commission Region IV, 1600 East Lamar Blvd Arlington, Texas 76011-4511</p>
--	---

3. DOCKET NUMBER 030-28683	4. LICENSE NUMBER 49-23182-01	5. DATE OF INSPECTION August 11, 2014
-------------------------------	----------------------------------	--

**LICENSEE:**  
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.
- Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

*LC 17 requires a lock either on the gauge or its outer container to prevent unauthorized or accidental removal of the source from its shielded position.*

*Troxler gauge #20993 model 3440, did not have a lock on its operating mechanism. The lock was immediately placed on the gauge by the RSO*

**Licensee's Statement of Corrective Actions for Item 4, above.**

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Cody Schatz	<i>Cody A. Schatz</i>	8/11/14
NRC INSPECTOR	Don Stearns	<i>Donald L Stearns</i>	8/11/14
BRANCH CHIEF	G. Michael Vasquez	<i>G. M. Vasquez</i>	9/15/2014