

NRC INSPECTION MANUAL

DIRS

Change Notice 14-029

DELETED:

TRANSMITTED:

| <u>Number</u> | <u>Date</u> | <u>Number</u> | <u>Date</u> |
|----------------|-------------|---------------|-------------|
| 1. IMC 0310 | 12/19/13 | IMC 0310 | 12/04/14 |
| 2. IP 71111.01 | 11/09/09 | IP 71111.01 | 12/04/14 |
| 3. | | | |

TRAINING: No

REMARKS: IMC 0310, 'Aspects Within the Cross Cutting Areas,' has been editorially revised to provide a reference and link to NUREG-2165, "Safety Culture Common Language."

IP 71111.01, "Adverse Weather Protection," has been editorially revised to delete Subsection 02.04.c.7, "Sources of potential internal flooding that are not analyzed or not adequately maintained, for example failure of flexible piping expansion joints, failure of fire protection system sprinklers, roof leaks, rest room backups, and failure of service water lines," which already exists in IP 71111.06, and is no longer needed in IP 71111.01

DISTRIBUTION: Standard

END

Issue Date: 12/04/14

1

14-029