

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

<p>1. LICENSEE/LOCATION INSPECTED:</p> <p>Core Laboratories, Inc. dba Pro Technics division of Core Laboratories 6510 West Sam Houston Parkway North Houston, Texas 77041 Location: Alaska Department of Natural Resources, Deadhorse Track 57 Prudhoe Bay, Alaska</p> <p>REPORT NO: 030-30429/2014-001</p>	<p>2. NRC/REGIONAL OFFICE</p> <p>U.S. Nuclear Regulatory Commission Region IV 1600 East Lamar Boulevard Arlington, Texas 76011-4511</p>
---	---



<p>3. DOCKET NUMBER 030-30429</p>	<p>4. LICENSE NUMBER 42-26928-01</p>	<p>5. DATES OF INSPECTION August 12 through October 29, 2014</p>
---------------------------------------	--	--

LICENSEE:
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.
 - Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):
- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	R. Rick Muñoz		09/29/2014
BRANCH CHIEF	G. Michael Vasquez		11/25/2014

Non-Public
 Sensitive – Security-Related
 Public
 Non-Sensitive

Munoz, Rick

From: Munoz, Rick
Sent: Wednesday, October 29, 2014 12:53 PM
To: Williams, Will
Cc: Munoz, Rick
Subject: RE: ProTechnics Alaska Paperwork
Attachments: SecureZIP Attachments.zip

Will,

I am sending you a pdf file of a clear inspection report on NRC Form 591-M which documents the inspection of a temporary job site on the north slope at Brooks Range in Prudhoe Bay, Alaska. The inspection was conducted on August 12, 2014 with continued in office review through October 29, 2014. If you have any questions about the inspection or the 591-M please call me at (817) 200-1220.

Kindest Regards,

Rick Munoz

From: Williams, Will [<mailto:Will.Williams@corelab.com>]
Sent: Thursday, October 02, 2014 4:13 PM
To: Munoz, Rick
Subject: RE: ProTechnics Alaska Paperwork

No problem.

Will Williams

D: 713-328-2325 / M: 713-328-2320
C: 713-516-7392 / F: 713-328-2163

will.williams@corelab.com / www.corelab.com/protechnics

From: Munoz, Rick [<mailto:Rick.Munoz@nrc.gov>]
Sent: Thursday, October 02, 2014 4:04 PM
To: Williams, Will
Subject: RE: ProTechnics Alaska Paperwork

Will,

Thanks for the information. I will review them and get back to you soon I hope.

Regards,

Rick Muñoz
Nuclear Materials Inspector

U.S. Nuclear Regulatory Commission, Region-IV
1600 East Lamar Boulevard
Arlington, Texas 76011-4511

Office: (817) 200-1220
Cell: (512) 773-8520
Fax: (817) 200-1188
Email: rick.munoz@nrc.gov

The information contained in this message may be privileged and/or confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please notify the sender immediately by replying to the message and deleting the material from any computer.

Note: Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of the Nuclear Regulatory Commission, Region-IV or the Nuclear Materials Safety Branch-A. All e-mails are subject to monitoring and archival.

Finally, the recipient should check this message and any attachments for the presence of viruses. The Nuclear Regulatory Commission accepts no liability for any damage caused by any virus transmitted by this e-mail.

From: Williams, Will [<mailto:Will.Williams@corelab.com>]
Sent: Thursday, October 02, 2014 3:46 PM
To: Munoz, Rick
Subject: ProTechnics Alaska Paperwork

Rick,

Sorry this is late.

Here are the documents you requested. I did receive the original paperwork for the job so I have attached that also.

- Page 1 is Quarterly inventory
- Page 2 is Facility and Storage survey
- Page 3 is RA Receiving Log
- Page 4 is Receiving wipe form
- Page 5 is RA Use Log
- Page 6 is Utilization
- Page 7 & 8 are Job Site Surveys

If you need any additional information please let me know.

Will Williams
Director of US Operations
Core Lab
ProTechnics Division

D: 713-328-2325 / M: 713-328-2320
C: 713-516-7392 / F: 713-328-2163

6510 W. Sam Houston Pkwy N./ Houston, TX 77041

will.williams@corelab.com / www.corelab.com/protechnics