NRC FORM 591M PART 1 (07-2012)*			1	J.S. NUCLEAR REGI	ULATORY COMMISSION
10 CFR 2 201	FETY INSPECT	TION REPORT	AND COMPLIANCE I	NSPECTION	
1. LICENSEE/LOCATION INSPECTED: Geisser Engineering Corporation 227 Wampanoag Trail Riverside, RI 02915-2211 REPORT NUMBER(S) 2014-001			NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713		
3. DOCKET NUMBER(S)	2014-001	CENSE NUMBER(S		5. DATE(S) OF INSPECTION	
15000038			sland - Agreement State)	1	
identified, non-repetitivi exercise discretion, well Non-cited viola	and regulations ards, interviews with findings, no violations and control of the same of t	nd the conditions of personnel, and obsions were identified. ou by the inspector ction was or is being used involving the following the following the following the following. This for the following	your license. The inspection ervations by the inspector. as non-cited violations, are taken, and the remaining cooling requirement(s) and the inspector and are taken.	n consisted of selective. The inspection finding not being cited because riteria in the NRC Enforcerective action(s):	ve examinations of its are as follows: se they were self- orcement Policy, to
1	St	atement of Co	rrective Actions		
I hereby state that, within 30 days, the corrective actions is made in accorda- date when full compliance will be ach	nce with the require	ements of 10 CFR 2	2.201 (corrective steps alrea	dy taken, corrective s	steps which will be taken,
Title	P	rinted Name		Signature	Date
LICENSEE'S REPRESENTATIVE	teaux I.	LEISER	711		12/5/14
NRC INSPECTOR	John Miller	and the second s	Jing	Meller	12/5/14
BRANCH CHIEF	Blake Welling		Blik	Well_	12/8/14
*NRC FORM 591M PART 1 (07-2012) (RI Rev. 09/12/20	013) G:	\WordDocs\Current\Insp Re	cord\RRI3L-050-0120	14001.591M-Part1.doc
SUNSI Review Completed By:		John Miller		X Public	X Non-Sensitive