

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

<p>1. LICENSEE/LOCATION INSPECTED:</p> <p>Sterling Diagnostics, Inc. 36645 Metro Court Sterling Heights, MI 48310</p> <p>REPORT NUMBER(S) 14-001</p>	<p>2. NRC/REGIONAL OFFICE</p> <p>Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352</p>	
<p>3. DOCKET NUMBER(S)</p> <p>030-31055</p>	<p>4. LICENSE NUMBER(S)</p> <p>21-26030-01</p>	<p>5. DATE(S) OF INSPECTION</p> <p>December 17, 2014</p>

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

_____ Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Deborah A. Piskura		12/17/14
BRANCH CHIEF	Aaron T. McCraw, Chief, MIB		12/22/14

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Sterling Diagnostics, Inc. 36645 Metro Court Sterling Heights, MI 48310 REPORT NUMBER(S) 14-001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S) 030-31055	4. LICENSE NUMBER(S) 21-26030-01	5. DATE(S) OF INSPECTION December 17, 2014
--------------------------------------	---	---

6. INSPECTION PROCEDURES USED 87126	7. INSPECTION FOCUS AREAS 03.01- 03.07
--	---

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03244	2. PRIORITY 5	3. LICENSEE CONTACT Noli Cruz, RSO	4. TELEPHONE NUMBER (586) 979-2141
---------------------------------	----------------------	---	---

Main Office Inspection Next Inspection Date: Dec. 2019

Field Office Inspection _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

This was routine inspection of a small private company authorized to receive, store, and distribute diagnostic in-vitro kits containing I-125. These kits were distributed to its customers (general licensees) on an as needed basis. Approximately 100 kits were distributed annually.

This inspection consisted of interviews with licensee personnel, a review of select records, a tour of the kit storage area, and independent measurements. The inspector performed a confirmatory inventory of kits in the licensee's warehouse and compared the total activity with the licensee's possession limit listed on the NRC license. The inspector also reviewed the licensee's corrective actions for a violation of License Condition 11.B. (Radiation Safety Officer) identified during the previous inspection. The licensee filed an amendment to appoint a new RSO the following week after the inspection. The violation is considered closed.

No violations of NRC requirements were identified during this inspection.