



CERTIFICATE OF DISPOSITION OF MATERIALS

Brid

Estimated burden per response to comply with this mandatory collection request: 30 minutes. This submittal is used by NRC as part of the basis for its determination that the facility is released for unrestricted use. Send comments regarding burden estimate to the FOIA, Privacy, and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to InfoCollect.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NECEB-10202, (3150-0028), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

LICENSEE NAME AND ADDRESS
GMZ ASSOCIATES INC
115 GLASTONBURY BOULEVARD
GLASTONBURY, CT 06033

LICENSE NUMBER
0631472-01

DOCKET NUMBER
03038536

LICENSE EXPIRATION DATE
4/30/2022

A. LICENSE STATUS (Check the appropriate box)

- This license has expired. This license has not yet expired; please terminate it.

B. DISPOSAL OF RADIOACTIVE MATERIAL

(Check the appropriate boxes and complete as necessary. If additional space is needed, provide attachments)

The licensee, or any individual executing this certificate on behalf of the licensee, certifies that:

- 1. No radioactive materials have ever been procured or possessed by the licensee under this license.
- 2. All activities authorized by this license have ceased, and all radioactive materials procured and/or possessed by the licensee under this license number cited above have been disposed of in the following manner.
 - a. Transfer of radioactive materials to the licensee listed below:
SEAMAN NUCLEAR CORPORATION
 - b. Disposal of radioactive materials:
 - 1. Directly by the licensee:
 - 2. By licensed disposal site:
 - 3. By waste contractor:
 - c. All radioactive materials have been removed such that any remaining residual radioactivity is within the limits of 10 CFR Part 20, Subpart E, and is ALARA.

RECEIVED 02/28/2017

C. SURVEYS PERFORMED AND REPORTED

- 1. A radiation survey was conducted by the licensee. The survey confirms:
 - a. the absence of licensed radioactive materials
 - b. that any remaining residual radioactivity is within the limits of 10 CFR 20, Subpart E, and is ALARA.
- 2. A copy of the radiation survey results:
 - a. is attached; or b. is not attached (Provide explanation); or c. was forwarded to NRC on: _____ Date
- 3. A radiation survey is not required as only sealed sources were ever possessed under this license, and
 - a. The results of the latest leak test are attached; and/or
 - b. No leaking sources have ever been identified.

The person to be contacted regarding the information provided on this form:

NAME	TITLE	TELEPHONE (Include Area Code)	E-MAIL ADDRESS
JOSHUA SCOTT	RSO	860-659-1416	JScott@gmzinc.com

Mail all future correspondence regarding this license to:

JOSHUA SCOTT, GMZ ASSOCIATES, 115 GLASTONBURY BLVD, GLASTONBURY, CT 06033

C. CERTIFYING OFFICIAL

I CERTIFY UNDER PENALTY OF PERJURY THAT THE FOREGOING IS TRUE AND CORRECT

PRINTED NAME AND TITLE	SIGNATURE	DATE
JOSHUA SCOTT		1/23/15

WARNING: FALSE STATEMENTS IN THIS CERTIFICATE MAY BE SUBJECT TO CIVIL AND/OR CRIMINAL PENALTIES. NRC REGULATIONS REQUIRE THAT SUBMISSIONS TO THE NRC BE COMPLETE AND ACCURATE IN ALL MATERIAL RESPECT. 18 U.S.C. SECTION 1001 MAKES IT A CRIMINAL OFFENSE TO MAKE A WILLFULLY FALSE STATEMENT OR REPRESENTATION TO ANY DEPARTMENT OR AGENCY OF THE UNITED STATES AS TO ANY MATTER WITHIN ITS JURISDICTION.

Seaman Nuclear Corporation

7315 South First Street Oak Creek, WI 53154 USA

Tel 414-762-5100 Fax 414-762-5106

info@seamannuclear.com

Leak Test Certificate

January 13, 2015

A leak test has been performed on meter, serial number **21042**, a model C-300 DT, 8", containing the radionuclide Ra 226

Owned By: GM2 Associates
115 Glastonbury Blvd.
Glastonbury, CT 06033

Date Sample Collected: 1/9/15
Collected By: Josh Scott
Date Sample Analyzed: 1/12/15
Analyzed By: K. Krysiak

Most regulatory agencies consider a source to be leaking if a leak test reveals the presence of more than 0.005 microcurie of removable contamination.


Analysis found contamination of less than 0.005 microcurie.

Analysis authorized by Wisconsin license 079-1257-01.

LEAK TEST DUE: 7/9/15

^W


Scott C. Seaman
Radiation Safety Officer
Seaman Nuclear Corporation

S/N: 21042
Leak Tested: 1/12/15
Due: 7/9/15
 Seaman Nuclear Corporation
Oak Creek, WI (414) 762-5100

Seaman Nuclear Corporation

7315 South First Street Oak Creek, WI 53154 USA

Tel 414-762-5100 Fax 414-762-5106

info@seamannuclear.com

Leak Test Certificate

January 13, 2015

A leak test has been performed on meter, serial number **21178**, a model C-300 DT, 8", containing the radionuclide Ra 226

Owned By: GM2 Associates
115 Glastonbury Blvd.
Glastonbury, CT 06033

Date Sample Collected: 1/9/15
Collected By: Josh Scott
Date Sample Analyzed: 1/12/15
Analyzed By: K. Krysiak

Most regulatory agencies consider a source to be leaking if a leak test reveals the presence of more than 0.005 microcurie of removable contamination.

Analysis found contamination of less than 0.005 microcurie.

Analysis authorized by Wisconsin license 079-1257-01.

LEAK TEST DUE: 7/9/15




Scott C. Seaman
Radiation Safety Officer
Seaman Nuclear Corporation

S/N: 21178

Leak Tested: 1/9/15

Due: 7/9/15

 Seaman Nuclear Corporation
Oak Creek, WI (414) 762-5100



115 GLASTONBURY BOULEVARD
GLASTONBURY, CT 06033


HARTFORD CT 061

31 JAN 2015 PM 7 L



LICENSING ASSISTANT SECTION
NUCLEAR MATERIALS SAFETY BRANCH
U.S. NUCLEAR REGULATORY COMMISSION,
REGION 1
2100 RENAISSANCE BOULEVARD, SUITE 100
KING OF PRUSSIA, PA 19406-2713

19406271325



This is to acknowledge the receipt of your letter/application dated

1/23/15, and to inform you that the initial processing which includes an administrative review has been performed.

Termination (06-31472-01) There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number** 585996.
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.