

# USER INSTRUCTIONS FOR ULTRAVIOLET TANNING LAMPS

**Sunlamp - DANGER - Ultraviolet Radiation.  
Follow Instructions**

Avoid overexposure. As with natural sunlight, overexposure can cause eye and skin injury and allergic reactions. Repeated exposure may cause premature aging of the skin and skin cancer.

Contraindication: This sunlamp product is contraindicated for use on persons under the age of 18 years.

Contraindication: This sunlamp product must not be used if skin lesions or open wounds are present.

Warning: This sunlamp product should not be used on individuals who have had skin cancer or have a family history of skin cancer.

Warning: Persons repeatedly exposed to ultraviolet sunlamp products should be regularly evaluated for skin cancer.

## **WEAR PROTECTIVE EYEWEAR; FAILURE TO MAY RESULT IN SEVERE BURNS OR LONG-TERM INJURY TO THE EYES.**

Medications or cosmetics may increase your sensitivity to the ultraviolet radiation. Consult physician before using sunlamp if you are using medications or have a history of skin problems or believe yourself especially sensitive to sunlight. If you do not tan in the sun, you are unlikely to tan from the use of this product."

**Use ONLY in fixture equipped with a timer.**

**Use ONLY in fixture equipped with an appropriate protective filter.**

Always follow the instructions accompanying the sunlamp equipment to minimize potential injury. Use only with products where this lamp is specified as replacement or original equipment by the sunlamp product manufacturer.

The lamp operates at an overpressure so that the possibility of an explosion cannot be entirely excluded.

The quartz bulb should be free from contaminations such as fingerprints.

Contamination may be removed with methylated spirit.

The manufacturer cannot accept any responsibility for personal injury or damage to equipment which may result from improper use of the lamp or from using improper equipment.

This product is conformity with the performance standards for sunlamp products under 21 CFR 1040.20

Imported and Distributed by:  
Superior UV Technologies  
25 Carriage Drive  
Easton, CT 06612  
(888) 526-7712

contains Kr-85  
contains Hg



Made in Hungary