

Rio Tinto

Kennecott Uranium Company
42 Miles NW of Rawlins
P.O. Box 1500
Rawlins, WY 82301-1500
USA
T +1 (307) 328 1476
F +1 (307) 324 4925

25 February 2015

Mr. Andrew Persinko, Deputy Director
Division of Waste Management & Environmental Protection
Office of Federal & State Materials & Environmental Management Programs
11545 Rockville Pike
Rockville, MD 20852-2738

Dear Mr. Persinko:


**SUBJECT: Sweetwater Uranium Project – Docket Number 40-8584
Source Material License No. SUA-1350 – Annual Corrective Action
Program Review and Groundwater Monitoring Report**

Enclosed is a CD-ROM containing Kennecott Uranium Company's Annual Corrective Action Program Review for 2013.

The report summarizes all monitoring and mitigation efforts in the area of the tailings cell under the ground water corrective action program, as defined in License Condition 11.3 of USNRC Source Materials License SUA-1350, and contains the ground water monitoring data required to be submitted under License Condition 12.3.

If you have any questions, please do not hesitate to contact me at (307) 328-1476.

Sincerely,



Oscar A. Paulson
Facility Supervisor

cc: James Webb, Project Manager – USNRC
Director – NRC DRSS – Region IV (w/o enc)
Deborah Harris, PG, Wyoming Department of Environmental Quality
GPC West District Supervisor
Water Quality Division
510 Meadowview Drive
Lander, WY 82520

OSM#1:

001-Airborne Effluents-40.65-2014.pdf	11.4 MB
002-Annual ALARA Audit-2014.pdf	12.8 MB
003-Land Use Report 2014.pdf	6.45 MB
004-Annual CorrectiveActionProgramReview-2014.pdf	116 MB
❖ Cover Letter	262 KB
❖ Appendix 1	262 KB
❖ Appendix 2	8.31 MB
❖ Appendix 3	5.26 MB
❖ Appendix 4	16.6 MB
❖ Diesel Excavation and Catchment Basin Monitor Wells	231 KB
❖ Maps	28.5 MB
❖ Tables	308 KB
❖ Tailings Monitor Wells.....	23.7 MB

Kennecott Uranium Company
Source Material License #SUA-1350, License Condition 12.3
Docket Number 40-8584
Reports for period January – December 2014
Submittal dated: 25 February 2015