NRC FORM 591M PART 1 (07-2012)* 10 CFR 2.201	ETY INS	PECTION REPORT	AND COM			ATORY COMMISSION
LICENSEE/LOCATION INSPECTED: Department of the Army U.S. Army Communications-Electronics Command 1215 Industrial Road Mitchell, South Dakota 57301 REPORT NUMBER(S) 2015001			NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713			
		4. LICENSE NUMBER(3 19-31447-01			5. DATE(S) OF INSPECTION March 17, 2015	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X						
I hereby state that, within 30 days, the corrective actions is made in accordar date when full compliance will be achi	nce with the	requirements of 10 CFR	ector will be to 2.201 (correct	aken to correct ctive steps alrea	dy taken, corrective ste	eps which will be taken,
Title		Printed Name	·		Signature	Date
LICENSEE'S REPRESENTATIVE					J	
NRC INSPECTOR	Don Stearns, Health Physicis		st	/RA KModes f/		3/23/2015
BRANCH CHIEF Marc S. Ferdas, Chief			/RA/		3/30/2015	
*NRC FORM 591M PART 1 (07-2012) (RI Rev. 0	9/12/2013) G:	\WordDocs\C	urrent\Insp Rec	ord\R19-31447-01.201	5001-591MPart1.doc
SUNSI Review Completed By:	/RA/	D. Stearns			X Public	X Non-Sensitive