

# CATEGORY 1

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9703050055 DOC. DATE: 97/02/26 NOTARIZED: NO  
FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.  
50-270 Oconee Nuclear Station, Unit 2, Duke Power Co.  
50-287 Oconee Nuclear Station, Unit 3, Duke Power Co.  
72-0004 Oconee ISFSI, 50-269, 50-270 & 50-287,

DOCKET #  
05000269  
05000270  
05000287  
07200004

AUTH. NAME AUTHOR AFFILIATION  
HAMPTON, J.W. Duke Power Co.  
RECIP. NAME RECIPIENT AFFILIATION  
Document Control Branch (Document Control Desk)

SUBJECT: Informs that completion of LEOC17 refueling outage tentatively scheduled for 970928 re response to violations noted in Insp Repts 50-269/96-09, 50-270/96-09, 50-287/96-09 & 72-0004/96-09.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2  
TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

### NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 PD	1 1	LABARGE, D	1 1
	KOBETZ, T	1 1	BRINKMAN, D	1 1
INTERNAL:	ACRS	2 2	AEOD/SPD/RAB	1 1
	AEOD/TTC	1 1	DEDRO	1 1
	<u>FILE CENTER</u>	1 1	NRR/DISP/PIPB	1 1
	NRR/DRCH/HHFB	1 1	NRR/DRPM/PECB	1 1
	NRR/DRPM/PERB	1 1	NUDOCS-ABSTRACT	1 1
	OE DIR	1 1	OGC/HDS2	1 1
	RGN2 FILE 01	1 1		
EXTERNAL:	LITCO BRYCE, J H	1 1	NOAC	1 1
	NRC PDR	1 1	NUDOCS FULLTEXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:  
PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
ROOM OWFN 5D-5 (EXT. 415-2083) TO ELIMINATE YOUR NAME FROM  
DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 22 ENCL 0

IAE

C  
A  
T  
E  
G  
O  
R  
Y  
  
1  
  
D  
O  
C  
U  
M  
E  
N  
T

Duke Power Company  
Oconee Nuclear Site  
P.O. Box 1439  
Seneca, SC 29679

J. W. HAMPTON  
Vice President  
(864)885-3499 Office  
(864)885-3564 Fax



**DUKE POWER**

February 26, 1997

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, DC 20555


Subject: Oconee Nuclear Site  
Docket Nos. 50-269,-270,-287; 72-4  
Inspection Report 50-269,-270,-287/96-09  
Revised Reply to Notice of Violation

By letter dated June 27, 1996, the NRC issued a Notice of Violation as related to an NRC inspection conducted from April 21 - June 1, 1996.

In our response to Violation 96-09-01, we committed to implement modifications to remove the accumulation of moisture in the Hydrogen Recombiner piping by August 1, 1997. This commitment date was based on a schedule for completing the Unit 1 EOC 17 refueling outage by August 1, 1997. The modifications are complete on Units 2 and 3.

Because of the Unit 1 forced outage from October 4, 1996, to February 12, 1997, the next refueling outage on Unit 1 has been delayed until after August 1, 1997. The modification is still scheduled to be completed during the next Unit 1 refueling outage. The completion of the 1EOC17 refueling outage is tentatively scheduled for September 28, 1997.

Very truly yours,

  
J. W. Hampton

IEA 1/0

050005

Attachments

9703050055 970226  
PDR ADOCK 05000269  
G PDR



Document Control Desk

February 26, 1997

Page 2

cc: Mr. L. A. Reyes, Regional Administrator  
U. S. Nuclear Regulatory Commission, Region II

Mr. Dave LaBarge, Project Manager  
Office of Nuclear Reactor Regulation

Mr. M. A. Scott, Senior Resident Inspector  
Oconee Nuclear Site