

*Central File*

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

31 MAR 24 A 8: 1'

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

March 20, 1981

TELEPHONE: AREA 704  
373-4083

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303



Re: RII:JPO  
50-269-270-287  
I.E. Bulletin 81-01

Dear Sir:

Your letter dated January 27, 1981, which transmitted I.E. Bulletin 81-01, requested a response concerning the surveillance of mechanical snubbers. Since Oconee Nuclear Station has none of the INC snubbers identified in the bulletin, items 1 and 2 of the subject bulletin do not apply. In response to your request concerning item 3, Duke Power completed a full inspection of the Unit 3 inaccessible mechanical snubbers on February 20, 1981, per bulletin requirements. Everything was clean. The Unit 1 and Unit 2 inaccessible mechanical snubbers will be done during the next refueling outage for each unit. The inspection of Unit 1, Unit 2, and Unit 3 accessible mechanical snubbers will be completed by May 31, 1981.

I declare under penalty of perjury that the statements set forth herein are true and correct to the best of my knowledge, executed on March 20, 1981.

Very truly yours,

*William O. Parker, Jr.*  
William O. Parker, Jr.

JLJ:pw

cc: Director  
Division of Reactor Operations Inspection  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8103310913

Q