

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8805020065 DOC. DATE: 88/04/22 NOTARIZED: NO
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.
 AUTH. NAME TUCKER, H. B. AUTHOR AFFILIATION Duke Power Co.
 RECIP. NAME RECIPIENT AFFILIATION

DOCKET # 05000269

Document Control Branch (Document Control Desk)

SUBJECT: Advises that LER 269/88-04 submitted by 880406 ltr re emergency power switching logic retransfer to startup logic will be revised. Util now evaluating new info re incident.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: AEOD/Ornstein:1cy.

05000269

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
	PD2-3 LA	1	PD2-3 PD	1
	PASTIS, H	1		
INTERNAL:	ACRS MICHELSON	1	ACRS MOELLER	2 2
	AEOD/DOA	1	AEOD/DSP/NAS	1
	AEOD/DSP/ROAB	2 2	AEOD/DSP/TPAB	1
	ARM/DCTS/DAB	1 1	DEDRO	1
	NRR/DEST/ADS 7E	1 0	NRR/DEST/CEB 8H	1
	NRR/DEST/ESB 8D	1	NRR/DEST/ICSB 7	1
	NRR/DEST/MEB 9H	1	NRR/DEST/MTB 9H	1
	NRR/DEST/PSB 8D	1 1	NRR/DEST/RSB 8E	1
	NRR/DEST/SGB 8D	1 1	NRR/DLPQ/HFB 10	1
	NRR/DLPQ/QAB 10	1 1	NRR/DOEA/EAB 11	1
	NRR/DREP/RAB 10	1 1	NRR/DREP/RPB 10	2 2
	NRR/DRIS/SIB 9A	1	NRR/PMAS/ILRB12	1 1
	<u>REG FILE</u> 02	1	RES TELFORD, J	1 1
	RES/DE/EIB	1	RES/DRPS DIR	1 1
	RGN2 FILE 01	1		
EXTERNAL:	EG&G GROH, M	4 4	FORD BLDG HOY, A	1
	H ST LOBBY WARD	1	LPDR	1
	NRC PDR	1	NSIC HARRIS, J	1
	NSIC MAYS, G	1 1		
NOTES:		1 1		

TOTAL NUMBER OF COPIES REQUIRED: LTR 46 ENCL 0
 45

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

April 22, 1988


U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D. C. 20555

Subject: Oconee Nuclear Station
Docket Nos. 50-269, -270, -287
LER 269/88-04

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a)(1) and (d), Licensee Event Report (LER) 269/88-04 was submitted to your office by letter dated April 6, 1988. LER 269/88-04 concerned Emergency Power Switching Logic retransfer to startup logic. Duke is evaluating new information regarding this incident and will revise the LER as necessary.

Very truly yours,



Hal B. Tucker

PJN/2/sbn

xc: Dr. J. Nelson Grace
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Ms. Helen Pastis
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

M&M Nuclear Consultants
1221 Avenue of the Americas
New York, New York 10020

American Nuclear Insurers
c/o Dottie Sherman, ANI Library
The Exchange, Suite 245
270 Farmington Avenue
Farmington, CT 06032

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

Mr. P. H. Skinner
NRC Resident Inspector
Oconee Nuclear Station

8805020065 880422
PDR ADCK 05000269
S PDR

IER 2
10