ACCELERATED DOCUMENT DISTRIBUTION SYSTEM REGULATEY INFORMATION DISTRIBUTION SYSTEM (RIDS)				
ACCESSION NBR:9305200351 FACIL:50-269 Oconee Nucle 50-270 Oconee Nucle 50-287 Oconee Nucle AUTH.NAME AUTHOR HAMPTON,J.W. Duke Pov	DOC.DATE: 9 ear Station, 1 ear Station, 1 ear Station, 1 AFFILIATION wer Co.	93/05/13 NOTARIZED Unit 1, Duke Power Unit 2, Duke Power Unit 3, Duke Power	D: NO Co. Co.	DOCKET # 05000269 05000270 05000287 R
RECIP.NAME RECIPIENT AFFILIATION Document Control Branch (Document Control Desk) I				
SUBJECT: Forwards "Degraded Grid & Switchyard Isolation Functional D				
Test" procedure & Calculation OSC-5337, "10CFR50.59 Evaluation for PT/O/A/0610/21, 'Degraded Grid & Switchyard S Isolation Functional Test.'"				
DISTRIBUTION CODE: A001D COPIES RECEIVED:LTR \perp ENCL \perp SIZE: $1 + 3 + 7$				
NOTES:			÷.	А
RECIPIENT	COPIES	RECIPIENT	COPIES	D
ID CODE/NAME PD2-3 LA WIENS,L	LTTR ENCL 1 1 2 2	ID CODE/NAME PD2-3 PD	LTTR ENCL 1 1	, D
INTERNAL: ACRS NRR/DORS/OTSB NRR/DSSA/SCSB NRR/DSSA/SRXB OC/LFMB REG FILE 01	6 6 1 1 1 0 1 1 1 0 1 1	NRR/DE/EELB NRR/DRCH/HICB NRR/DSSA/SPLB NUDOCS-ABSTRACT OGC/HDS2	1 1 1 1 1 1 1 1 1 1 1 0	S

1 1 NSIC

EXTERNAL: NRC PDR

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 22 ENCL 19

D

R

I

D

S

1

Α

D

1

.... I.

1

S

Duke Power Company Oconee Nuclear Site P.O. Box 1439 Seneca, SC 29679 J. W. HAMPTON Vice President (803)885-3499 Office (803)885-3564 Fax



DUKE POWER

May 13, 1993

U. S. Nuclear Regulatory Commission Attention: Document Control Desk Washington, DC 20555

Subject: Oconee Nuclear Station Docket Nos. 50-269,-270,-287 Overhead Emergency Power Path Testing

Attached for your information is copy of the approved degraded grid and switchyard isolation functional test procedure. The associated 50.59 evaluation is included. It is anticipated that this test will be performed on May 22, 1993 during the Oconee Unit 2 refueling outage. In the event of significant changes to this procedure, the NRC Resident Inspectors will be notified of the changes prior to the test.

Very Truly Yours,

M Daviá

W. Hampton

xc:

P. E. Harmon, Senior Resident Inspector Oconee Nuclear Station

L. A. Wiens, Project Manager ONRR

S. D. Ebneter, Regional Administrator Region II

200045

