

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8301040327 DOC. DATE: 82/12/23 NOTARIZED: NO DOCKET #
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co. 05000269
 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co. 05000270
 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co. 05000287

AUTH. NAME AUTHOR AFFILIATION
 TUCKER, H.B. Duke Power Co.
 RECIP. NAME RECIPIENT AFFILIATION
 DENTON, H.R. Office of Nuclear Reactor Regulation, Director
 STOLZ, J.F. Operating Reactors Branch 4

SUBJECT: Corrects errors in 821119 revisions to inservice testing program, per ASME Boiler & Pressure Vessel Code, 1980 edition through Winter 1980 addenda. Valve ICCW-289 & Valves 1, 2 & 3 HP-402 should be indicated as check valves.

DISTRIBUTION CODE: A047S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1
 TITLE: OR Submittal: Inservice Inspection/Testing

NOTES: AEOD/Ornstein:1cy. 05000269
 AEOD/Ornstein:1cy. 05000270
 AEOD/Ornstein:1cy. 05000287

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	NRR ORB4 BC 01	7 7	NRR CLIMBERG, R	1 0
INTERNAL:	ELD/HDS4	1 0	NRR/DE/MEB	15 1 1
	NRR/DE/MTEB 14	1 1	<u>REG FILE</u>	04 1 1
	RGN2	1 1		
EXTERNAL:	ACRS 16	10 10	LPDR 03	1 1
	NRC PDR 02	1 1	NSIC 05	1 1
	NTIS	1 1		
NOTES:		1 1		

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

December 23, 1982

TELEPHONE
(704) 373-4531

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

Mr. H. R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Mr. J. F. Stolz, Chief
Operating Reactors Branch No. 4

Subject: Oconee Nuclear Station
Docket Nos. 50-269, -270, -287

Dear Sir:

By letter dated November 19, 1982, Duke provided the NRC Staff revisions to the Oconee inservice testing program. This letter corrects certain minor errors that were contained in the above letter.

The applicable ASME Boiler and Pressure Vessel Code is the 1980 Edition through Winter 1980 Addenda. In the table of changes to the inservice testing program attached to the above letter, two minor changes are required. Valve ICCW-289 should be indicated as a check valve rather than stroke test and valves 1, 2, 3 HP-402 should be indicated as check valves.

If there are any questions regarding this please advise through the normal licensing channels.

Very truly yours,

H. B. Tucker / AS

Hal B. Tucker

RLG:scs

cc: Mr. J. P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Mr. E. L. Conner, Jr.
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector
Oconee Nuclear Station

8301040327 821223
PDR ADDCK 05000269
P PDR

A047