

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8001140421      DOC. DATE: 80/01/07      NOTARIZED: NO      DOCKET #  
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.      05000269  
 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co.      05000270  
 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co.      05000287

AUTH. NAME      AUTHOR AFFILIATION  
 PARKER, W.O.      Duke Power Co.  
 RECIP. NAME      RECIPIENT AFFILIATION  
 REID, R.W.      Operating Reactors Branch 4

SUBJECT: Forwards revised pages to "AFW Sys Reliability Analysis: Generic Rept for B&W Designed Plant."

DISTRIBUTION CODE: A041S      COPIES RECEIVED: LTR 1 ENCL 1      SIZE: 1+2  
 TITLE: Resp to Lesson Learn Task Force - B&W and 50-409

NOTES: M. CUNNINGHAM - ALL AMENDS TO FSAR & CHANGES TO TECH SPECS.

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL	ID CODE/NAME	LTR	ENCL
	8 BC ORB #4	7	7			
INTERNAL:	1 REG FILE	1	1	15 I & E	2	2
	17 TAYLOR	1	1	18 CORE PERF BR	1	1
	19 ENG BR	1	1	2 NRC PDR	1	1
	20 REAC SFTY BR	1	1	21 PLANT SYS BR	1	1
	22 EEB	1	1	23 EFLT TRT SYS	1	1
	3 LPDR	1	1	4 NSIC	1	1
	5 C LONG	1	1	6 G LANIK	1	1
	7 J DONOHEW	1	1	J.T. TELFORD	2	2
	0 CHOPRA	1	1	DELD	1	0
EXTERNAL:	24 AGRS	16	16			

JAN 15 1980

MA  
4

TOTAL NUMBER OF COPIES REQUIRED: LTR 43 ENCL 42

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

January 7, 1980

TELEPHONE: AREA 704  
373-4083

Mr. Harold R. Denton, Director  
Office of Nuclear Reactor Regulation  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555


Attention: Mr. R. W. Reid, Chief  
Operating Reactors Branch No. 4

Re: Oconee Nuclear Station  
Docket Nos. 50-269, -270, -287

Dear Sir:

My letter of December 21, 1979, described steps to be taken to improve the reliability of the Oconee emergency feedwater system, and transmitted to your office a report entitled "Auxiliary Feedwater Systems Reliability Analysis: A Generic Report for Babcock & Wilcox Designed Plants." Subsequent to that submittal, errors were found in the presentation of the results for the loss of offsite power case (Case 2) for Crystal River 3. Therefore, attached are revised Figures 1B and B1, which should be substituted for pages 19 and B-4, respectively, in the report previously submitted.

Very truly yours,



William O. Parker, Jr.

SRL/sch  
Attachments



April 5/11

8001140421