

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8003310318 DOC. DATE: 80/03/14 NOTARIZED: NO DOCKET #  
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co. 05000269  
 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co. 05000270  
 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co. 05000287  
 AUTH. NAME AUTHOR AFFILIATION  
 \* Duke Power Co.  
 RECIPIENT NAME RECIPIENT AFFILIATION

SUBJECT: Press release discussing facilities removal from svc for mods re TMI short-term Lessons Learned requirements.

DISTRIBUTION CODE: H001S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: DCD Material

NOTES: ~~M. CUNNINGHAM - ALL AMENDMENTS TO FSAR~~  
~~T CHANGES TO TECH SPECS R. CAPRA - IC~~

	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID	CODE/NAME	LTR	ENCL	ID	CODE/NAME	LTR	ENCL
INTERNAL:	01	REG FILE	1	1	02	NRC PDR	1	1
EXTERNAL:	03	LPDR	1	1	04	NSIC	1	1

ADD:  
 ORB # 4 BC  $\frac{L}{4}$   $\frac{E}{0}$

APR 2 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR

9 ENCL. 0

MA  
4

March 14, 1980

From: Corporate Communications Department  
Duke Power Company  
422 South Church Street  
Charlotte, North Carolina 28242

WALHALLA, S.C. --- Duke Power Co. will remove its Oconee Nuclear Station's Unit No. 3 from service Saturday as ordered by the Nuclear Regulatory Commission, Austin C. Thies, senior vice president, production and transmission, said today.

Unit No. 3 is expected to be off line for about three weeks while Duke Power makes modifications related to lessons learned from the Three Mile Island accident.

Unit No. 2 was taken off line last week for refueling, to allow work required by NRC bulletins to be done and to perform remaining changes ordered in the aftermath of TMI. Unit No. 2 is expected to be back in service in late spring.

Unit No. 1 has been refueled and is at full power.

Duke Power's reserves will be about 8 percent this month and in early April because of the unavailability of the two Oconee units.

Although the reserves will be less than Duke Power would prefer, the company believes it can provide adequate service without resorting to emergency calls for conservation, voltage reductions or rotating blackouts, Thies said.

--00--

AH003014080

Distribution: A, B, C

For further information, call Angie Howard at 704/373-8138.

*Handwritten:*  
Hoor  
5/0  
AW:  
ORB # 4 DE 40 LE

8003310318