



**UNITED STATES
NUCLEAR REGULATORY COMMISSION**

REGION III
2443 WARRENVILLE RD. SUITE 210
LISLE, IL 60532-4352

September 1, 2015

Mr. Bryan C. Hanson
Senior VP, Exelon Generation Co., LLC
President and CNO, Exelon Nuclear
4300 Winfield Road
Warrenville, IL 60555

**SUBJECT: MID-CYCLE ASSESSMENT LETTER FOR BYRON STATION, UNITS 1 AND 2
(REPORT 05000454/2015005; 05000455/2015005)**

Dear Mr. Hanson:

On August 13, 2015, the U.S. Nuclear Regulatory Commission (NRC) completed its mid-cycle performance review of Byron Station, Units 1 and 2. The NRC reviewed the most recent quarterly performance indicators (PIs) in addition to inspection results and enforcement actions from July 1, 2014 through June 30, 2015. This letter informs you of the NRC's assessment of your facility during this period and its plans for future inspections at your facility.

The NRC determined that overall, Byron Station, Units 1 and 2, operated in a manner that preserved public health and safety and met all cornerstone objectives. The NRC determined the performance at Byron Station, Units 1 and 2, during the most recent quarter was within the Licensee Response Column of the NRC's Reactor Oversight Process (ROP) Action Matrix because all inspection findings had very low (i.e., green) safety significance, and all PIs indicated that your performance was within the nominal, expected range (i.e., green). Therefore, the NRC plans to conduct ROP baseline inspections at your facility.

The enclosed inspection plan lists the inspections scheduled through December 31, 2017. Routine inspections performed by resident inspectors are not included in the inspection plan. The inspections listed during the second half of the inspection plan are tentative and may be revised at the end-of-cycle performance review. The NRC provides the inspection plan to allow for the resolution of any scheduling conflicts and personnel availability issues. The NRC will contact you as soon as possible to discuss changes to the inspection plan should circumstances warrant any changes. This inspection plan does not include security related inspections, which will be sent via separate, non-publicly available correspondence.

In response to the accident at Fukushima, the Commission issued Order EA-12-049, "Order Modifying Licenses with Regard to Requirements for Mitigation Strategies for Beyond-Design-Basis External Events," which requires licensees to develop, implement, and maintain guidance and strategies to maintain or restore core cooling, containment, and spent fuel pool cooling capabilities following a beyond-design-basis external event. Additionally, the Commission issued Order EA-12-051, "Order Modifying Licenses with Regard to Reliable Spent Fuel Pool Instrumentation," which requires licensees to have a reliable means of remotely monitoring wide-range Spent Fuel Pool levels to support effective prioritization of event mitigation and recovery actions in the event of a beyond-design-basis external event. The NRC is conducting audits of licensee efforts towards compliance with these Orders. The audit has

been completed for the first unit at Byron, and the information gathered will aid staff in development of the ultimate Safety Evaluation for the site. After the NRC staff receives the Final Compliance letter for the site, the Final Safety Evaluation will be issued. Then, the NRC staff will confirm through inspections the full implementation of the orders mentioned above performing Temporary Instruction 191, "Inspection of the Implementation of Mitigation Strategies and Spent Fuel Pool Instrumentation Orders and Emergency Preparedness Communication/Staffing/Multi-Unit Dose Assessment Plans".

In accordance with Title 10 of the *Code of Federal Regulations* (10 CFR) 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's Agencywide Documents Access and Management System (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Please contact me at 630-826-9620 with any questions you have regarding this letter.

Sincerely,

/RA/

Eric Duncan, Chief
Branch 3
Division of Reactor Projects, Region III

Docket Nos. 50-454; 50-455
License Nos. NPF-37; NPF-66

Enclosure:
Byron Station, Units 1 and 2
Inspection/Activity Plan

cc w/encl: Distribution via LISTSERV®

been completed for the first unit at Byron, and the information gathered will aid staff in development of the ultimate Safety Evaluation for the site. After the NRC staff receives the Final Compliance letter for the site, the Final Safety Evaluation will be issued. Then, the NRC staff will confirm through inspections the full implementation of the orders mentioned above performing Temporary Instruction 191,"Inspection of the Licensee's Responses to Mitigation Strategies Order EA-12-049, Spent Fuel Pool Instrumentation Order EA-12-051 and Emergency Preparedness Information requested by NRC in March 12, 2012."

In accordance with Title 10 of the *Code of Federal Regulations* (10 CFR) 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's Agencywide Documents Access and Management System (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Please contact me at 630-826-9620 with any questions you have regarding this letter.

Sincerely,
/RA/
Eric Duncan, Chief
Branch 3
Division of Reactor Projects, Region III

Docket Nos. 50-454; 50-455
License Nos. NPF-37; NPF-66

Enclosure:
Byron Station, Units 1 and 2
Inspection/Activity Plan

cc w/encl: Distribution via LISTSERV®

DISTRIBUTION w/encl:

Kimyata MorganButler
RidsNrrDorLpl3-2 Resource
RidsNrrPMByron Resource
RidsNrrDirslrib Resource
Cynthia Pederson
Darrell Roberts
Richard Skokowski
Allan Barker

Carole Ariano
Linda Linn
DRPIII
DRSIII
Jim Clay
Carmen Olteanu
ROPAssessment.Resource@nrc.gov

ADAMS Accession Number: **ML15239B298**

Publicly Available Non-Publicly Available Sensitive Non-Sensitive

OFFICE	RIII	RIII	RIII	RIII
NAME	CHunt:tr	EDuncan		
DATE	8/27/2015	8/27/2015		

OFFICIAL RECORD COPY

Byron
Inspection / Activity Plan
09/01/2015 - 12/31/2017

Unit Number	Planned Dates		Inspection Activity	Title	No. of Staff on Site
	Start	End			
			BI ISI - INSERVICE INSPECTION UNIT 1		2
1	09/14/2015	10/09/2015	IP 7111108P	Inservice Inspection Activities - PWR	
			BI RP - RADIATION PROTECTION BASELINE INSPECTION		1
1	10/19/2015	10/23/2015	IP 71124.03	In-Plant Airborne Radioactivity Control and Mitigation	
1	10/19/2015	10/23/2015	IP 71124.04	Occupational Dose Assessment	
			BI RP - RADIATION PROTECTION BASELINE INSPECTION		1
1	11/16/2015	11/20/2015	IP 71124.05	Radiation Monitoring Instrumentation	
			OL PREP - INIT PREP/FEB 2016		3
1	02/15/2016	02/19/2016	W90325	OL - INITIAL EXAM - 2016 FEB-MAR - BYRON	
			OL EXAM - INIT EXAM/MARCH 2016		3
1	03/14/2016	03/25/2016	W90325	OL - INITIAL EXAM - 2016 FEB-MAR - BYRON	
			ISI - INSERVICE INSPECTION ON UNIT 2		2
2	04/18/2016	05/20/2016	IP 7111108P	Inservice Inspection Activities - PWR	
			BI RP - RADIATION PROTECTION BASELINE INSPECTION		2
1	04/25/2016	04/29/2016	IP 71124.01	Radiological Hazard Assessment and Exposure Controls	
1	04/25/2016	04/29/2016	IP 71124.02	Occupational ALARA Planning and Controls	
1	04/25/2016	04/29/2016	IP 71124.03	In-Plant Airborne Radioactivity Control and Mitigation	
1	04/25/2016	04/29/2016	IP 71124.04	Occupational Dose Assessment	
			ENG BI - TRIENNIAL FIRE PROTECTION		3
1, 2	06/06/2016	07/08/2016	IP 7111105T	Fire Protection [Triennial]	
			BI RP - RADIATION PROTECTION BASELINE INSPECTION		2
1	06/27/2016	07/01/2016	IP 71124.06	Radioactive Gaseous and Liquid Effluent Treatment	
1	06/27/2016	07/01/2016	IP 71124.08	Radioactive Solid Waste Processing and Radioactive Material Handling, Storage, and Transportation	
1	06/27/2016	07/01/2016	IP 71151	Performance Indicator Verification	
			ISFSI - ISFSI CASK LOADING INSPECTION		1
1, 2	10/01/2016	10/28/2016	IP 60855.1	Operation of an Independent Spent Fuel Storage Installation at Operating Plants	
			BI EP - EP BASELINE INSPECTION / PI VERIFICATION		1
1, 2	10/03/2016	10/07/2016	IP 7111402	Alert and Notification System Testing	
1, 2	10/03/2016	10/07/2016	IP 7111403	Emergency Preparedness Organization Staffing and Augmentation System	
1, 2	10/03/2016	10/07/2016	IP 7111405	Correction of Emergency Preparedness Weaknesses and Deficiencies	
1, 2	10/03/2016	10/07/2016	IP 71151	Performance Indicator Verification	
			BI HS - TRIENNIAL HEAT SINK INSPECTION		2
1, 2	10/24/2016	10/28/2016	IP 7111107T	Heat Sink Performance	

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.

Byron
Inspection / Activity Plan
09/01/2015 - 12/31/2017

Unit Number	Planned Dates		Inspection Activity	Title	No. of Staff on Site
	Start	End			
			OL-RQ - BIENNIAL REQUAL PROGRAM INSPECTION		2
1, 2	12/05/2016	12/09/2016	IP 7111111B	Licensed Operator Requalification Program	
			BI RP - RADIATION PROTECTION BASELINE INSPECTION		1
1	02/27/2017	03/03/2017	IP 71124.05	Radiation Monitoring Instrumentation	
			ISI - INSERVICE INSPECTION UNIT 1		1
1	03/06/2017	04/01/2017	IP 7111108P	Inservice Inspection Activities - PWR	
			BI ENG - TRIENNIAL MODIFICATIONS/5059 INSPECTION		3
1, 2	05/15/2017	06/02/2017	IP 7111117T	Evaluations of Changes, Tests, and Experiments and Permanent Plant Modifications	
			BI PI&R - BIENNIAL PI&R INSPECTION		1
1, 2	07/10/2017	07/28/2017	IP 71152B	Problem Identification and Resolution	
			BI EP - EP EXERCISE INSPECTION / PI VERIFICATION		5
1, 2	07/24/2017	07/28/2017	IP 7111401	Exercise Evaluation	
1, 2	07/24/2017	07/28/2017	IP 7111406	Drill Evaluation	
1, 2	07/24/2017	07/28/2017	IP 7111408	Exercise Evaluation – Scenario Review	
1, 2	07/24/2017	07/28/2017	IP 71151	Performance Indicator Verification	
			TI191 - FLEX/MITIGATING STRATEGIES/SFPI		4
1	08/28/2017	09/01/2017	IP 2515/191	Inspection of Licensee's Responses to Order EA-12-049, EA-12-051 & EP Info Request March 12, 2012	
			ISI - INSERVICE INSPECTION UNIT 2		1
2	10/02/2017	10/23/2017	IP 7111108P	Inservice Inspection Activities - PWR	

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.