

PMTurkeyCOLPEm Resource

From: Franzone, Steve [Steve.Franzone@fpl.com]
Sent: Tuesday, August 25, 2015 1:42 PM
To: Comar, Manny
Cc: Patel, Pravin; Burkhardt, Lawrence; TurkeyCOL Resource; Maher, William
Subject: [External_Sender] RE: Inconsistency in response to Rai 3.7.1-15

Yes, we will investigate issue and let you know the results along with any further action.

Thanks

Steve Franzone

NNP Licensing Manager - COLA

“Stand up to your obstacles and do something about them. You will find that they haven't half the strength you think they have.” ~ Norman Vincent Peale

561.694.3209 (office)

754.204.5996 (cell)

“This transmission is intended to be delivered only to the named addressee(s) and may contain information that is confidential and /or legally privileged. If this information is received by anyone other than the named addressee(s), the recipient should immediately notify the sender by E-MAIL and by telephone (561.694.3209) and permanently delete the original and any copy, including printout of the information. In no event shall this material be read, used, copied, reproduced, stored or retained by anyone other than the named addressee(s), except with the express consent of the sender or the named addressee(s).

From: Comar, Manny [mailto:Manny.Comar@nrc.gov]
Sent: Tuesday, August 25, 2015 1:15 PM
To: Franzone, Steve
Cc: Patel, Pravin; Burkhardt, Lawrence; TurkeyCOL Resource
Subject: Inconsistency in response to Rai 3.7.1-15

This is an EXTERNAL email. Exercise caution. DO NOT open attachments or click links from unknown senders or unexpected email.

Steve:

In RAI 3.7.1-15, Letter L-2015-085, Attachment 2, Page 109 and 125 of 172, the GMRS is described as being located at elevation -35 ft. This is consistent with the description included in letter L-2015-085, App 3JJ.

While reviewing Attachment 2, Enclosure 2, p. 19 of 231 of the same letter, 2nd paragraph, it states that the GMRS is developed at El -16 ft. and it refers to Figures 2.5.2-253 and 254 of the FSAR.

One of them is incorrect or typo?

Please clarify discrepancy through voluntary response.

Thanks

Manny Comar
Senior Project Manager

Nuclear Regulatory Commission
Office of New Reactors
301-415-3863
Manny.comar@nrc.gov

Hearing Identifier: TurkeyPoint_COL_Public
Email Number: 1086

Mail Envelope Properties (DEC707C5CF603B4AA6194131A65C7C52449D2A58)

Subject: [External_Sender] RE: Inconsistency in response to Rai 3.7.1-15
Sent Date: 8/25/2015 1:41:35 PM
Received Date: 8/25/2015 1:41:38 PM
From: Franzone, Steve

Created By: Steve.Franzone@fpl.com

Recipients:

"Patel, Pravin" <Pravin.Patel@nrc.gov>
Tracking Status: None
"Burkhart, Lawrence" <Lawrence.Burkhart@nrc.gov>
Tracking Status: None
"TurkeyCOL Resource" <TurkeyCOL.Resource@nrc.gov>
Tracking Status: None
"Maher, William" <William.Maher@fpl.com>
Tracking Status: None
"Comar, Manny" <Manny.Comar@nrc.gov>
Tracking Status: None

Post Office: GOXSA1809.fplu.fpl.com

Files	Size	Date & Time
MESSAGE	2081	8/25/2015 1:41:38 PM

Options

Priority: Standard
Return Notification: No
Reply Requested: No
Sensitivity: Normal
Expiration Date:
Recipients Received: