

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8607100316 DOC. DATE: 86/06/27 NOTARIZED: NO DOCKET #
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co. 05000269
 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co. 05000270
 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co. 05000287

AUTH. NAME AUTHOR AFFILIATION
 TUCKER, H. B. Duke Power Co.
 RECIP. NAME RECIPIENT AFFILIATION
 DENTON, H. R. Office of Nuclear Reactor Regulation, Director (post 851125
 STOLZ, J. F. PWR Project Directorate 6

SUBJECT: Forwards "Oconee Emergency Procedure Guideline: Inadequate Core Cooling Monitoring Instrumentation Guidance." Development of guidance delayed due to detailed reviews & discussions of proposed procedure changes. Fee paid.

DISTRIBUTION CODE: A002D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+13
 TITLE: OR Submittal: Inadequate Core Cooling (Item II.F.2) GL 82-28

NOTES: AEOD/Ornstein: lcy. 05000269
 AEOD/Ornstein: lcy. 05000270
 AEOD/Ornstein: lcy. 05000287

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PWR-B PD6 LA	1 1	PWR-B PD6 PD	1 1
	NICOLARAS, H	2 2	PWR-B RSB	1 1
INTERNAL:	ADM/LFMB	1 0	NRR BWR DIR	1 1
	NRR BWR PD1	1 1	NRR PWR-A DIR	1 1
	NRR PWR-B DIR	1 1	NRR SHEA, J 01	2 2
	NRR/DSRO EMRIT	1 1	NRR/DSRO/RSIB	1 1
	<u>REG FILES</u> 04	1 1	RGN2 07	1 1
EXTERNAL:	LPDR 03	1 1	NRC PDR 02	1 1
	NSIC 06	1 1		

NOTES: 1 1

Rec'd w/ check

TOTAL NUMBER OF COPIES REQUIRED: LTTR 20 ENCL 19

DUKE POWER COMPANY
P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

June 27, 1986

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Mr. John F. Stolz, Project Director
PWR Project Directorate No. 6

Subject: Oconee Nuclear Station
Docket Nos. 50-269, -270, -287

Dear Sir:

By letter dated November 23, 1983, the NRC provided its Safety Evaluation Report of the proposed Inadequate Core Cooling Instrumentation for Oconee Nuclear Station. Within the November 23, 1984 letter, the NRC requested certain schedular information. By letter dated June 4, 1985 Duke provided a revised implementation schedule which addressed the ten (10) milestones provided by enclosure 3 of the November 23, 1983 NRC letter. Item 2 identified the date to submit the Emergency Procedure Guidelines for NRC approval, which was March, 1986. However, the development of the guidance was delayed due to detailed reviews and discussions of the proposed procedure changes.

To this end, please find attached the Oconee Emergency Guidelines for the Inadequate Core Cooling Monitoring Instrumentation. This submittal, also, satisfies the requirement provided by Section III.5 of the "Order for Modification of License" dated December 10, 1982 which required that prior to use of the ICC Instrumentation System, Emergency Procedure Guidelines be submitted for NRC review and approval.


Pursuant to 10 CFR 170.12, please find attached the application fee of \$150.00.

Very truly yours,

Hal B. Tucker
Hal B. Tucker

PFG:slb

Attachment



Rec'd w/ checks

A002
1/1

Mr. Harold R. Denton, Director

June 27, 1986

Page Two

xc: Dr. J. Nelson Grace, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Mrs. Helen Pastis
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. J. C. Bryant
NRC Resident Inspector
Oconee Nuclear Station