

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

TELEPHONE
(704) 373-4531

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

July 31, 1987


U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D. C. 20555

Subject: Oconee Nuclear Station
Docket Nos. 50-269, -270, -287
Confirmatory Order Modifications

Dear Sir:

This letter is written to clarify statements made in the April 6, 1987 letter from Duke Power to the NRC. The Unit 1 RBCU and LPI coolers will be cleaned, tested and evaluated for full power operation prior to restarting the unit following the End-of-Cycle 10 refueling outage.

Very truly yours,



Hal B. Tucker

WHM/71/sbn

xc: Dr. J. Nelson Grace, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Ms. Helen Pastis
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. J. C. Bryant
NRC Resident Inspector
Oconee Nuclear Station

Mr. Heyward Shealy, Chief
Bureau of Radiological Health
South Carolina Department of Health &
Environmental Control
2600 Bull Street
Columbia, South Carolina 29201

*A001
110*

8708070191 870731
PDR ADDCK 05000269
P PDR