

Walt, Geralyn

From: Miller, John
Sent: Thursday, September 03, 2015 2:29 PM
To: KELLY.L.PETRILLO@DUPONT.COM
Subject: Request for Additional Information - Mail Control No. 588540

E.I DuPont De Nemours and Co., Inc.
License No. 07-13441-02
Docket No. 030-20681
Control No. 588540

Dear Ms. Petrillo

Your organization uses a Decommissioning Funding Plan (DFP) to determine the amount of financial assurance necessary to fund all decommissioning activities. Regulations set forth in 10 CFR 30.35(e)(2) require that, at the time of license renewal and at intervals not to exceed 3 years, the DFP must be resubmitted with adjustments as necessary to account for changes in costs and the extent of contamination. Your currently approved DFP was completed on April 27, 2012, and approved on December 31, 2012; therefore your DFP must be resubmitted. If the amount of financial assurance will be adjusted downward, this cannot be done until the updated DFP is approved by the NRC. The DFP must update the information submitted with the original or prior approved DFP, and must specifically consider the effect of the following events on decommissioning costs: (1) spills of radioactive material producing additional residual radioactivity in onsite subsurface material; (2) waste inventory increasing above the amount previously estimated; (3) waste disposal costs increasing above the amount previously estimated; (4) facility modifications; (5) changes in the authorized possession limits; (6) actual remediation costs that exceed the previous cost estimate; (7) onsite disposal; and the use of a settling pond. Please refer to NUREG-1757, Vol. 3, Rev. 1, Appendix A, Section A.3 for guidance.

<http://pbadupws.nrc.gov/docs/ML1204/ML12048A683.pdf>

I have reviewed your DFP dated April 27, 2012. I did not see a detailed cost for decommissioning the incinerator that is used to process radioactive waste. In your updated DFP, please provide a detailed assessment for decommissioning the incinerator as part of your overall decommissioning cost for your entire facility.

Please resubmit your updated DFP. You may submit the document by hard copy, or as a pdf copy attached to an email, or by facsimile to 610-337-5269. Please be sure to include the Control No. 588540 on your response. We would appreciate a response within 60 days.

Thank you for your cooperation.

John J. Miller
Health Physicist
Division of Nuclear Materials Safety

Phone: 610-337-5089
Fax: 610-337-5269
E-mail: john.miller@nrc.gov