



September 18, 2015
10 CFR 54

SBK-L-15170
Docket No. 50-443

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555-0001

Seabrook Station
Fifth Annual Update to the
NextEra Energy Seabrook License Renewal Application

References:

1. NextEra Energy Seabrook, LLC letter SBK-L-10077, "Seabrook Station Application for Renewed Operating License," May 25, 2010. (Accession Number ML101590099)
2. NextEra Energy Seabrook, LLC letter SBK-L-11773, "First Annual Update to the Seabrook License Renewal Application," August 25, 2011. (Accession Number ML11241A142)
3. NextEra Energy Seabrook, LLC letter SBK-L-12186, "Second Annual Update to the Seabrook License Renewal Application," September 18, 2012. (Accession Number ML12268A171)
4. NextEra Energy Seabrook, LLC letter SBK-L-13115, "Third Annual Update to the Seabrook License Renewal Application," July 2, 2013. (Accession Number ML13189A197)
5. NextEra Energy Seabrook, LLC letter SBK-L-13183, "Clarification to the Third Annual Update Provided in SBK-L-13115," October 21, 2013. (Accession Number ML13189A197)
6. NextEra Energy Seabrook, LLC letter SBK-L-14173, "Fourth Annual Update to the Seabrook License Renewal Application," October 2, 2014. (Accession Number ML14282A023)

In Reference 1, NextEra Energy Seabrook, LLC submitted an application for a renewed facility operating license for Seabrook Station Unit 1 in accordance with the Code of Federal Regulations, Title 10, Parts 50, 51, and 54.

A144
MRR

The License Renewal Rule, 10 CFR 54.21(b) requires that each year following submittal of a license renewal application (LRA), and at least 3 months before scheduled completion of the NRC review, an update to the LRA must be submitted that identifies any change to the current licensing basis (CLB) of the facility that materially affects the content of the LRA including the Updated Final Safety Analysis Report Supplement.

In accordance with the License Renewal Rule, NextEra Energy Seabrook, LLC has performed a fifth annual review of CLB changes since the submittal of the LRA, to determine whether any sections of the LRA were affected by these changes. The first, second, third and fourth annual review results are documented in References 2, 3, 4, 5 and 6. The fifth annual review did not identify any changes to the current licensing basis (CLB) of the facility that materially affected the content of the LRA including the Updated Final Safety Analysis Report Supplement.

This letter contains no revised or new commitments.


If there are any questions or additional information is needed, please contact Mr. Edward J. Carley, Engineering Supervisor - License Renewal, at (603) 773-7957.

If you have any questions regarding this correspondence, please contact Mr. Michael H. Ossing Licensing Manager, at (603) 773-7512.

I declare under penalty of perjury that the foregoing is true and correct.

Executed on September 13, 2015.

Sincerely,



Dean Curtland
Site Vice President
NextEra Energy Seabrook, LLC

Enclosures: None

cc:	D. H. Dorman	NRC Region I Administrator
	J. G. Lamb	NRC Project Manager
	P. C. Cataldo	NRC Senior Resident Inspector
	R. A. Plasse	NRC Project Manager, License Renewal
	L. M. James	NRC Project Manager, License Renewal

Mr. Perry Plummer
Director Homeland Security and Emergency Management
New Hampshire Department of Safety
Division of Homeland Security and Emergency Management
Bureau of Emergency Management
33 Hazen Drive
Concord, NH 03305

Mr. John Giarrusso, Jr., Nuclear Preparedness Manager
The Commonwealth of Massachusetts
Emergency Management Agency
400 Worcester Road
Framingham, MA 01702-5399