

~~SAFEGUARDS INFORMATION~~

Enclosures 1 and 2 Contain ~~Safeguards Information Withhold Under 10 CFR 2.390~~

When separated from the ~~Safeguards Information~~ enclosures, the cover letter is DECONTROLLED provided the transmittal document does not warrant protection from unauthorized disclosure.



CONNECTICUT YANKEE ATOMIC POWER COMPANY

HADDAM NECK PLANT
362 INJUN HOLLOW ROAD • EAST HAMPTON, CT 06424-3099

September 15, 2015
CY-15-030

ATTN: Document Control Desk
U.S. Nuclear Regulatory Commission,
Washington, DC 20555

Connecticut Yankee Atomic Power Company
Haddam Neck Plant Independent Spent Fuel Storage Installation
NRC License Nos. DPR-61 and SFGL-21 (NRC Docket Nos. 50-213 and 72-39)

Subject: Revision to Response to Interim Compensatory Measures dated October 16, 2002

On October 16, 2002, the U.S. Nuclear Regulatory Commission (NRC) issued an order that modified the general license for the Haddam Neck Plant (HNP) Independent Spent Fuel Storage Installation (ISFSI) to require compliance with the specified interim safeguards and security compensatory measures (Reference 1). Connecticut Yankee Atomic Power Company (CYAPCO) submitted the final version of the HNP ISFSI implementation matrix for the Interim Compensatory Measures (ICMs) on May 3, 2004 (Reference 2). Via this letter, CYAPCO is submitting a revised HNP ISFSI implementation matrix for the ICMs dated October 16, 2002 (Enclosure 1). In addition, a summary of changes to the HNP ISFSI implementation matrix for the ICMs dated October 16, 2002 is provided in Enclosure 2.

The enclosures contain Safeguards Information. It is therefore requested that this information be withheld from public disclosure in accordance with 10 CFR 2.390, "Public Inspections, Exemptions, Requests for Withholding," paragraph (d)(1), and 10 CFR 73.22, "Protection of Safeguards Information: Specific Requirements," paragraph (a)(4). When detached from Enclosures 1 and 2, this cover letter does not contain Safeguards Information and may be decontrolled.

~~SAFEGUARDS INFORMATION~~

Enclosures 1 and 2 Contain ~~Safeguards Information Withhold Under 10 CFR 2.390~~

When separated from the ~~Safeguards Information~~ enclosures, the cover letter is DECONTROLLED provided the transmittal document does not warrant protection from unauthorized disclosure.

5001
NM5526

~~SAFEGUARDS INFORMATION~~

Enclosures 1 and 2 Contain ~~Safeguards Information Withhold Under 10 CFR 2.390~~

When separated from the ~~Safeguards Information~~ enclosures, the cover letter is DECONTROLLED provided the transmittal document does not warrant protection from unauthorized disclosure.

Connecticut Yankee Atomic Power Company
CY-15-030/September 15, 2015/Page 2 of 2

If you have any question regarding this submittal, please do not hesitate to contact me at (860) 267-6426.

Respectfully,



Brantley Buerger, P.E.
ISFSI Manager

References:

1. M. Virgilio (NRC) letter to K. Heider (CYAPCO), Issuance of Order for Interim Safeguards and Security Compensatory Measures for Haddam Neck Plant, dated October 16, 2002.
2. Letter from W. Norton (CYAPCO) to Document Control Desk (NRC), Interim Compensatory Measures for Dry Independent Spent Fuel Storage Installation, dated May 3, 2004.

Enclosures:

1. HNP ISFSI Implementation Matrix for ICMs Issued October 16, 2002
 2. Summary of Changes to the HNP ISFSI Implementation Matrix for ICMs Issued October 16, 2002
- cc: D. H. Dorman, NRC Region I Administrator (Cover Letter Only)
M. S. Ferdas, Chief, Decommissioning Branch, NRC, Region I
J. Goshen, NRC Project Manager
J. Semancik, Director, CT DEEP, Radiation Division (Cover Letter Only)

~~SAFEGUARDS INFORMATION~~

Enclosures 1 and 2 Contain ~~Safeguards Information Withhold Under 10 CFR 2.390~~

When separated from the ~~Safeguards Information~~ enclosures, the cover letter is DECONTROLLED provided the transmittal document does not warrant protection from unauthorized disclosure.