

*The enclosure to this letter contain security-related information.
Withhold from public disclosure in accordance with 10 CFR 2.390*



October 16, 2015

10 CFR 73.71

Docket No. 50-443

SBK-L-15186

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555-0001

Seabrook Station
Licensee Event Report (LER) 2015-S01-00
Obstruction Discovered in Response Rifle

Enclosed is Licensee Event Report (LER) 2015-S01-00. This LER reports an event that occurred at Seabrook Station on August 22, 2015. This event is being reported pursuant to the requirements of 10 CFR 73.71(b).

The enclosure contains security-related information; therefore, NextEra requests that this submittal be withheld from public disclosure in accordance with 10 CFR 2.390(d)(1).

Should you require further information regarding this matter, please contact James Tucker, Security Manager at (603) 773-7354.

Sincerely,

NextEra Energy Seabrook, LLC

A handwritten signature in black ink, appearing to read "Dean Curtland".

Dean Curtland
Site Vice President

cc: NRC Region I Administrator
J. G. Lamb, NRC Project Manager
NRC Senior Resident Inspector

JE74
NRK