



Entergy[®]

Entergy Operations, Inc.

River Bend Station
5485 U.S. Highway 61N
St. Francisville, LA 70775
Tel 225-381-4177

Joseph A. Clark
Manager-Licensing

RBG-47589
RBF1-15-0107

July 13, 2015

Mr. Greg Warnick
U.S. Nuclear Regulatory Commission
Region IV
1600 E. Lamar Blvd.
Arlington, TX 76011-4511

Reference: NRC letter to Entergy, dated July 7, 2015, NRC Inspection Report
05000458/2015009; Preliminary White Finding

Subject: Response to Preliminary White Finding
River Bend Station – Unit 1
Docket No. 50-458
License No. NPF-47

Dear Mr. Warnick:

As requested in NRC Special Inspection Report 05000458/2015009, this letter is to inform the NRC of our intentions regarding the Preliminary White Finding for failure to maintain the simulator consistent with actual plant response for normal and transient conditions related to feedwater flows, alarm response, and behavior of the startup feedwater regulating valve controller. River Bend will submit its position on the preliminary finding to the NRC in writing.

Should you have any questions regarding this matter, please contact me at (225) 381-4177.

Sincerely,

JAC/KRH

IE01

Response to Preliminary White Finding
RBG-47589
Page 2 of 2

cc: U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

NRC Resident Inspector
PO Box 1050
St. Francisville, LA 70775

Ms. Tracie Lowrey
Public Utility Commission of Texas
1701 N. Congress Ave.
Austin, TX 78711-3326

Mr. Alan Wang, Project Manager
U.S. Nuclear Regulatory Commission
MS O-8B1
11555 Rockville Pike
Rockville, MD 20852-2738