



Byron Generating Station

4450 North German Church Rd  
Byron, IL 61010-9794

www.exeloncorp.com

November 20, 2015

10 CFR 72.44 (d)(3)

LTR: BYRON 2015-0143  
File: 1.10.0101 (1D.101)  
2.12.1522.01 (5F.110)

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Director, Spent Fuel Project Office  
Office of Nuclear Material Safety and Safeguards  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555-001

Byron Station, Units 1 and 2  
Facility Operating License Nos. NPF-37 and NPF-66  
NRC Docket Nos. STN 50-454 and STN 50-455

Subject: Byron Station Independent Spent Fuel Storage Installation  
Annual Radioactive Effluent Release Report

In accordance with 10 CFR 72.44 (d)(3) this letter provides the annual radioactive effluent release report for Byron Generating Station Independent Spent Fuel Storage Installation (ISFSI) for the period September 9, 2014 through September 9, 2015. During this period there were no radioactive effluents released from the Byron Nuclear Station Independent Spent Fuel Storage Installation.

Should you have any questions concerning this letter, please contact Mr. Douglas Spitzer, Regulatory Assurance Manager, at (815) 406-2800.

Respectfully,

A handwritten signature in blue ink, appearing to read "TDC", with a large flourish at the end.

Thomas D. Chalmers  
Plant Manager  
Byron Generating Station

TDC/AC/sg

cc: Regional Administrator – NRC Region III  
Senior NRC Resident Inspector – Byron Generating Station