

In the Matter of: Entergy Nuclear Operations, Inc.  
(Indian Point Nuclear Generating Units 2 and 3)

NYS000456  
Submitted: November 9, 2012



ASLBP #: 07-858-03-LR-BD01  
 Docket #: 05000247 | 05000286  
 Exhibit #: NYS000456-00-BD01  
 Admitted: 11/5/2015  
 Rejected:  
 Other:  
 Identified: 11/5/2015  
 Withdrawn:  
 Stricken:

### History of Steam Generators Indian Point Unit 2 and Unit 3

	IP2 (DPR-26)*	IP3 (DPR-64)**
Date of Initial 40-yr. Operating License	9/28/1973	12/12/1975
Date of Installation of Replacement Steam Generators at IP Unit 3	--	6/1989
Date of Tube Rupture of IP Unit 2 Steam Generator	2/15/2000	--
Date of Installation of Replacement Steam Generators at IP Unit 2	12/2000	--
Date of Expiration of 40-yr. Operating license	9/28/2013	12/12/2015
Years of Operations of Replacement Steam Generators at Expiration of 40-yr. Operating License	12.8 years	26.5 years

**\*Sources:**

- Appendix A, Volume 23, NUREG-1350, 2011-2012 Information Digest, August 2011 (NRCR00086)
- Indian Point Unit 2, NL-00-043. Letter from J. Baumstark, Consolidated Edison Company of New York to NRC, "Root Cause Evaluation for Steam Generator Tube Rupture Event of February 15, 2000," Apr. 14, 2000 (ENT000567)
- NRC OIG, NRC's Response to the February 15, 2000 Steam Generator Tube Rupture at Indian Point Unit 2 Power Plant, Case No. 00-03S (Aug. 29, 2000) (NYS000457)
- K. Karwoski to M. Khanna October 8, 2009 email and chart, Steam Generator Replacements Completed (NYS000458)

**\*\*Sources:**

- Appendix A, Volume 23, NUREG-1350, 2011-2012 Information Digest, August 2011 (NRCR00086)
- History of Westinghouse Model 44 Steam Generators (NYS000378)
- K. Karwoski to M. Khanna October 8, 2009 email and chart, Steam Generator Replacements Completed (NYS000458)