United States Nuclear Regulatory Commission Official Hearing Exhibit

In the Matter of: Entergy Nuclear Operations, Inc. (Indian Point Nuclear Generating Units 2 and 3)

ASLBP #: 07-858-03-I R-BD01 Docket #: 05000247 | 05000286 Exhibit #: NYS000553-00-BD01 Admitted:

Other:

11/5/2015 Rejected:

Identified: 11/5/2015 Withdrawn: Stricken:

NYS000553 Submitted: June 9, 2015

COMMITMENT CLOSURE VERIFICATION FORM

Sheet 1 of 2

LRS/CMS I.D. IP2- A-Source /Parent Document NL-11-032, NL-11-074, NL-10378 11-090, NL-11-096 IP3- A-10379 LO-LAR-2011-0174 CA IP2-60 LRC # 42 IP3-61

Commitment Summary Restate or paraphrase the commitment

IPEC will develop a plan for each unit to address the potential for cracking of the primary to secondary pressure boundary due to PWSCC of tube-to tubesheet welds using one of the following two options.

Option 1 (Analysis)

IPEC will perform an analytical evaluation of the steam generator tube-to-tubesheet welds in order to

establish a technical basis for either determining that the tubesheet cladding and welds are not susceptible to PWSCC, or redefining the pressure boundary in which the tube-to-tubesheet weld is no longer included and, therefore, is not required for reactor coolant pressure boundary function. The redefinition of the reactor coolant pressure boundary must be approved by the NRC as a license amendment request.

Option 2 (Inspection)

IPEC will perform a one-time inspection of a representative number of tube-to-tubesheet welds in each steam generator to determine if PWSCC cracking is present. If weld cracking is identified:

- a. The condition will be resolved through repair or engineering evaluation to justify continued service, as appropriate, and
- b. An ongoing monitoring program will be established to perform routine tube-to tubesheet weld inspections for the remaining life of the steam generators.

Extent of Closure Full | IP2 and IP3 Partial

Means of Closure List the closure documents (e.g., letter, procedure, etc.) from which

objective evidence of commitment closure can be obtained.1

LO-LAR-2011-00174 CA 60 for IP2 is being used to track commitment 42.

LO-LAR-2011-00174 CA 61 for IP3 is being used to track commitment 42.

Note 1: Objective evidence from the listed closure documentation must be attached or reference provided regarding where the documentation may be retrieved.

EN-LI-110-Att-9.2, Rev. 5

COMMITMENT CLOSURE VERIFICATION FORM

Sheet 2 of 2 Site License Renewal Project Manager Site Licensing The objective evidence supports the Extent of Closure indicated above AND the commitment tracking system has been updated. CLOSURE DATE for 182 is 2/29/2024 CLOSOPE 9978 fm) \$3.5 4/15/2017
Site Licensing Signature Ahllang CLOSURE -Indian Coint 2 - Technical Specification Cementment # 277 was issued by NRC on 9/5/14; see response to LR-LAR-2011-00174, CA60 growded by R. Dolansky on 9/17/14. Also RA-14-130. The objective evidence supports the Ettent of Closure for IPX Jonly AND the commitment wacking system has been updated Pall 10/15/14 Entergy

CORRECTIVE ACTION

LR-LAR-2011-00174

CA Number:

60

Assigned By: IP2 Projects Site Staff IP2 Caputo, Charles M

Assigned To: IP2 Eng Code Programs Staff IP2 Dolansky,Robert J

Subassigned To:

 Originated By:
 Caputo, Charles M
 8/23/2011 21:52:53

 Performed By:
 Dolansky,Robert J
 9/17/2014 09:11:06

Subperformed By: Approved By:

Current Due Date: 02/29/2024 Initial Due Date: 02/29/2024

CA Type: NRC COMMITMENT CA Priority:

Plant Constraint: OTHER

Closed By:

CA Description:

NRC Commitment #42

IPEC will develop a plan for each unit to address the potential for cracking of the primary to secondary pressure boundary due to PWSCC of tube-to-tubesheet welds using one of the following two options.

Option 1 (Analysis)

IPEC will perform an analytical evaluation of the steam generator tube-to-tubesheet welds in order to establish a technical basis for either determining that the tubesheet cladding and welds are not susceptible to PWSCC, or redefining the pressure boundary in which the tube-to-tubesheet weld is no longer included and, therefore, is not required for reactor coolant pressure boundary function. The redefinition of the reactor coolant pressure boundary must be approved by the NRC as a license amendment request.

Option 2 (Inspection)

IPEC will perform a one-time inspection of a representative number of tube-to-tubesheet welds in each steam generator to determine if PWSCC cracking is present. If weld cracking is identified:

- a. The condition will be resolved through repair or engineering evaluation to justify continued service, as appropriate, and
- b. An ongoing monitoring program will be established to perform routine tube-to-tubesheet weld inspections for the remaining life of the steam generators.

Response:

NRC Commitment 42 is complete for IP2.

IP2 has developed an alternate repair criteria for the steam generators, called H*, which has redefined the pressure boundary in which the tube-to-tubesheet weld is no longer included and, therefore, is not required for reactor coolant pressure boundary function. The application of H* was approved by the NRC as Technical Specification Amendment 277 which was issued by the NRC on September 5, 2014.

Subresponse:

Closure Comments: