

THE CHURCH OF
JESUS CHRIST
OF LATTER-DAY SAINTS

JEROME ID FM GROUP
P.O. Box 711
Jerome, Idaho 8338-0711
Phone 1-208-324-5097
Facsimile: 1-208-324-8941

Director of FSME
Attn: GLTS
USNRC
Washington, DC 20555-0001

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on October 30 2015 we transferred the self-luminous exit signs listed on the attached spreadsheet to SRBT, 320 Boundary Rd. , Suite 140, Pembroke, Ontario, K8A6W5, Canada with CNSC License #NSPFOL-13.00/2022. As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please contact Stephen K King 1-208-589-7996, or Clayton Pope 1-208-539-6283.

Sincerely



Stephen K. King

Encl.

SERIAL NUMBER SPREADSHEET

Company Name	Jerome IDAHO F.M. Group	Date	
Address 1	Box 711	Isolite RMA #	11581PA - RMA
Address 2	26 N 100 E	EWS Order #	-
Address 3		MTS Order #s	FMACQ - 171166
City/State	JEROME / IDAHO	Contact Name	STEPHEN K KING
Zip/Post Code	83338	Contact Phone	208-589-7996
Country	U.S.A.	Contact FAX	208-554-2018
		Contact E-mail	jfmsking@gmail.com

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"	
				Month	Year		
M M A C K A Y I D A H O ON SHELF	1	SRB TECHNOLOGIES	B 100	591030	05	95	MAXIMUM 20 Curies
	2	"	"	591031	05	95	"
	3	"	"	591032	05	95	"
	4	"	"	591033	05	95	"
	5	"	"	591034	05	95	"
	6	"	"	591035	05	95	"
	7	"	"	591036	05	95	"
	8	"	"	591037	05	95	"
	9	"	"	591038	05	95	"
	10	"	"	591039	05	95	"
	11	"	"	591020	05	95	"
	12	"	"	591021	05	95	"
	13	"	"	591022	05	95	"
	14	"	"	591023	05	95	"
	15	"	"	676776	08	02	"

*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs---not "ONE" Please make note of this.

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

SERIAL NUMBER SPREADSHEET

Company Name	JEROME IDAHO F.M. GROUP	Date	
Address 1	Box 711	Isolite RMA #	11581PA-RMA
Address 2	26 N 100E	EWS Order #	—
Address 3		MTS Order #s	FMACQ-171166
City/State	JEROME / IDAHO	Contact Name	STEPHEN K KING
Zip/Post Code	83338	Contact Phone	208-589-7996
Country	U.S.A.	Contact FAX	208-554-2018
		Contact E-mail	jfmsking@gmail.com

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"	
				Month	Year		
CH A L L I S I D MA MA ON STORAGE SHELF	1	SRB TECHNOLOGIES	B100	629138	04	98	MAX 20 Curies
	2	SRB TECHNOLOGIES	"	629139	04	98	"
	3	"	"	629140	04	98	"
	4	"	"	629141	04	98	"
	5	"	"	629142	04	98	"
	6	"	"	640408	02	99	"
	7	"	"	640409	02	99	"
	8	"	"	640410	02	99	"
	9	"	"	640411	02	99	"
	10	"	"	640412	02	99	"
	11	"	"	591048	05	95	"
	12	"	"	591049	05	95	"
	13	"	"	676961	09	02	"
	14	"	"	676962	09	02	"
	15	"	"	676970	09	02	"

*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs---not "ONE" Please make note of this.

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.