

NRC INSPECTION MANUAL

DIRS

Change Notice 15-032

DELETED:

TRANSMITTED:

<u>Number</u>	<u>Date</u>	<u>Number</u>	<u>Date</u>
1. IMC 0305	04/09/15	IMC 0305	12/23/15
2. IMC 0306	07/18/14	IMC 0306	12/23/15
3. TI 2515/191	10/06/14	TI 2515/191	12/23/15

TRAINING: No

REMARKS: IMC 0305, "Operating Reactor Assessment Program," has been revised to change the definition of Degraded Cornerstone, to make conforming changes resulting from the revised definition, and to change the title of Column 3 of the Action Matrix. Incorporated FBFs: 0305-1853, 1953, 2136, 2137, 2165, and 2170..

IMC 0306, "Planning, Tracking and Reporting of the Reactor Oversight Process (ROP)," has been revised to change the manual chapter title to be more descriptive, change substantive cross cutting issue (SCCI) to cross cutting issues (CCI) per feedback form 0306-2138. Added information regarding inspection item numbering in Section 05.03.b.2 to say that LINCVs will not be numbered as an item in an inspection report. Added text for counting LINCVs with a placeholder baseline procedure, and changed security and emergency preparedness assessment letters to inspection planning transmittal letters.

TI 2515/191, "Inspection of the Implementation of Mitigation Strategies and Spent Fuel Pool Instrumentation Orders and Emergency Preparedness Communication/Staffing/Multi-Unit Dose Assessment Plans," has been revised to incorporate Lessons Learned from the Watts Bar TI 191 pilot inspection completed in March 2015.

DISTRIBUTION:

- Standard
 Official Use Only (OUO)-Security Related Information.

Please contact: _____ Phone: _____

END