NUHOMS® EOS System Safety Analysis Report	Rev. 4, 12/15
NOTIONIS LOS SYSTEM SAICTY AMARYSIS REPORT	KCV. 4, 12/13
Proprietary Information on Pages 4-189 through 4-192 Withheld Pursuant to 10 CFR 2.390	




Figure 4-32
Temperature Distribution of EOS-TC125 Loaded with EOS-37PTH DSC at 50 kW, Normal Hot, Vertical Transfer Operations at 14 hours (Load Case # 1)
2 Pages




Figure 4-32
Temperature Distribution of EOS-TC125 Loaded with EOS-37PTH DSC at 50 kW, Normal Hot, Vertical Transfer Operations at 14 hours (Load Case # 1)
2 Pages





Figure 4-33
Temperature Distribution of EOS-TC125 Loaded with EOS-37PTH DSC at 50 kW, Normal Hot, Horizontal Transfer Operations at 14 hours (Load Case # 3)
2 Pages






Figure 4-33
Temperature Distribution of EOS-TC125 Loaded with EOS-37PTH DSC at 50 kW, Normal Hot, Horizontal Transfer Operations at 14 hours (Load Case # 3)
2 Pages




Figure 4-34
Temperature Distribution of EOS-TC125 Loaded with EOS-37PTH DSC at 36.35 kW, Load Case # 8
2 Pages




Figure 4-34
Temperature Distribution of EOS-TC125 Loaded with EOS-37PTH DSC at 36.35 kW, Load Case # 8
2 Pages