



Entergy Operations, Inc.  
1448 S.R. 333  
Russellville, AR 72802  
Tel 479-858-4704

**Stephenie L. Pyle**  
Manager, Regulatory Assurance  
Arkansas Nuclear One

1CAN011602

January 18, 2016

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

**SUBJECT:** Amended Inservice Inspection Summary Report for the  
Twenty-Fifth Refueling Outage (1R25)  
Arkansas Nuclear One – Unit 1  
Docket No. 50-313  
License No. DPR-51

**REFERENCE:** Entergy letter to the NRC, "Inservice Inspection Summary Report for the  
Twenty-Fifth Refueling Outage (1R25)," dated May 28, 2015 (1CAN051502)  
(ML15148A820)

Dear Sir or Madam:

Entergy Operations, Inc. (Entergy) submitted the required inservice inspection summary report for the Arkansas Nuclear One, Unit 1, Twenty-Fifth (1R25) refueling outage via the above reference. This report is to be prepared at the completion of a refueling outage and submitted within 90 calendar days of the completion of the refueling outage. This outage was completed on March 1, 2015.

The referenced submittal contained a completed Owner's Activity Report Form OAR-1. Included with the form were tables listing the "Items with Flaws or Relevant Conditions That Required Evaluation for Continued Service" and "Abstract of Repair / Replacement Activities Required for Continued Service."

In the "Certificate of Conformance" section of the OAR-1 form, Entergy had added the following note:

The NIS-2A form for R&R Plan number 52509981-03 could not be completed as documented in CR-ANO1-2015-02154. This R&R plan has no effect on Table 1 or Table 2 or this OAR. An amended OAR will be issued when the NIS-2A form for R&R Plan number 52509981-03 has been completed.

AD47  
NRR

The NIS-2A form for R&R Plan number 52509981-03 has been completed. The purpose of this submittal is to provide the amended OAR-1 form. The amended form is attached.

This letter contains no new commitments.

Should you have any questions regarding this submittal, please contact me.

Sincerely,



SLP/rwc

Attachment: Amended Form OAR-1, Owner's Activity Report

cc: Mr. Marc L. Dapas  
Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV  
1600 East Lamar Boulevard  
Arlington, TX 76011-4511

NRC Senior Resident Inspector  
Arkansas Nuclear One  
P. O. Box 310  
London, AR 72847

U. S. Nuclear Regulatory Commission  
Attn: Ms. Andrea E. George  
MS O-8B1  
One White Flint North  
11555 Rockville Pike  
Rockville, MD 20852

**Attachment to**

**1CAN011602**

**Amended Form OAR-1  
Owner's Activity Report**

**FORM OAR-1 OWNER'S ACTIVITY REPORT**

Report Number QAR-1431 Revision 1

Plant Arkansas Nuclear One / 1448 S.R. 333, Russellville, AR. 72802

Unit No. 1 Commercial service date December 19, 1974 Refueling outage no. 1R25  
(If applicable)

Current inspection interval Fourth (4<sup>th</sup>) Inspection Interval  
(1st, 2nd, 3rd, 4th, other)

Current inspection period Third (3rd) Inspection Period  
(1st, 2nd, 3rd)

Edition and Addenda of Section XI applicable to the inspection plan 2001 Edition with 2003 Addenda


Date and revision of inspection plan July 18, 2013 / Revision 0 (SEP-ISI-ANO1-101) and January 27, 2015 / Revision 1 (SEP-ISI-ANO1-101)

Edition and Addenda of Section XI applicable to repairs and replacements, if different than the inspection plan Same

Code Cases used: N-532-4, N-513-3  
(if applicable)

**CERTIFICATE OF CONFORMANCE**


I certify that (a) the statements made in this report are correct; (b) the examinations, tests meet the Inspection Plan as required by the ASME Code, Section XI; and (c) the repair/replacement activities and evaluations supporting the completion of 1R25 conform to the requirements of Section XI.  
(refueling outage number)

Signed Derek Varvil  ASME Section XI Repair/Replacement Engineer Date 12/8/2015  
Owner or Owner's Designee, Title

**CERTIFICATE OF INSERVICE INSPECTION**

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and the State or Province of Arkansas and employed by The Hartford Steam Boiler Inspection and Insurance Company of Hartford, Connecticut have inspected the items described in this Owner's Activity Report, and state that to the best of my knowledge and belief, the Owner has performed all activities represented by this report in accordance with the requirements of Section XI.

By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the repair/replacement activities and evaluation described in this report. Furthermore, neither the inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.

 Commissions 14374, ARK-1569, A, N, I  
Inspector's Signature National Board, State, Province, and Endorsements  
Date 12/15/15