

## UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV 1600 EAST LAMAR BLVD ARLINGTON, TEXAS 76011-4511

## EMAIL.



License: 05-14892-02

Docket: 030-08754

Control: 588333

Name:

Dr. Richard Graham

Radiation Safety Officer

Organization:

U.S. Environmental Protection Agency

Region 8

Phone:

303-312-7080

E-mail Address:

graham.richardv@epa.gov

From:

Jacqueline D. Cook January 19, 2016

Date: Subject:

Application dated June 29, 2015, for License Renewal

Pages:

Dr. Graham:

Per your application dated June 29, 2015, the items on the next page requires your response or clarification. I apologize for the short turnaround time but please respond to this e-mail by close of business Thursday, January 21, 2016. If you need more time to respond, please let me know of an alternate date to respond.

Our fax number is (817) 200-1263. You may respond by e-mail in pdf format if you'd like. My email address is <a href="mailto:Jackie.Cook@nrc.gov">Jackie.Cook@nrc.gov</a>. When responding to this e-mail, please include the license, docket and control numbers located at the top of this page.

Thanking you in advance for your cooperation, assistance, and prompt response in this matter.

IRAI Jacqueline D. Cook Senior Health Physicist Immediate Release **Normal Release** 

NON-PUBLIC

☐ A.3 Sensitive-Security Related

☐ A.7 Sensitive Internal

□ Other:

\_ Date: TAIL

1. Please note that "general licensed" check sources are not specifically line listed on your specific license.

Please confirm your understanding of the above.

2. Please note that the NRC does not list an "Alternate Radiation Protection Officer" in a license. The Radiation Safety Officer (RSO) is responsible for the overall management of the radiation safety program; identifying radiation safety problems, initiating, recommending or providing corrective actions; verifying implementation of corrective actions; ensuring compliance with the Commission's rules and regulations and conditions of the license. An RSO should actively participate in the day-to-day management of the radiation safety program. Although the performance of certain radiation safety tasks may be delegated by the RSO to other individuals (such as an alternate Radiation Safety Officer), the responsibility for the overall effectiveness of the radiation safety program and for compliance with NRC rules and regulations and conditions of the license reside with the RSO.

Please confirm your understanding of the above.

3. With the issuance of amendment number 27 to license number 05-14892-02, dated November 12, 2014, please note that we reviewed your current gas chromatograph inventory and based on your statement and a verification of the corresponding sealed source and device registration certificates determined that you are no longer in possession of specifically licensed gas chromatographs. Therefore, the authorization for the use of Ni-63 in specifically licensed gas chromatographs has been removed from the license with the issuance of amendment number 27.

Please confirm this statement, as appropriate.

