

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL  
(TEMPORARY FORM)**

CONTROL NO: 14091  
FILE: INCIDENT REPORT FILE

FROM: Duke Power Co. Charlotte, N.C. 28242 Wm. O. Parker, Jr.			DATE OF DOC 12-17-75	DATE REC'D 12-19-75	LTR XX	TWX	RPT	OTHER
TO: Mr. Norman C. Moseley			ORIG	CC 1	OTHER	SENT AEC PDR XX SENT LOCAL PDR XX		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-287		

DESCRIPTION: Ltr furnishing addl info to Unusual Event 287/75-10....

PLANT NAME: Oconee Unit 3

ENCLOSURES:

~~Do Not Remove~~  
**ACKNOWLEDGED**

**FOR ACTION/INFORMATION**

DHL 12-23-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/3 Copies	YOUNGBLOOD (E) W/ Copies	REID W/ Copies

**INTERNAL DISTRIBUTION**

<u>REG FILE</u> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE	TECH REVIEW SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	DENTON **GRIMES GAMMILL KASTNER BALLARD SPANGLER  ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR  HARLESS	LIC ASST R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	A/T IND BRAITMAN SALTZMAN MELTZ  PLANS MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
---	---	--	--	---

**EXTERNAL DISTRIBUTION**

1 - LOCAL PDR Walhalla, S.C.	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
16 ACRS SENT TO LIC ASST Sheppard 12-23-75		
** SEND ONLY TEN DAY REPORTS		

*MS*

DUKE POWER COMPANY

Regulatory Docket File

POWER BUILDING


422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

December 17, 1975

TELEPHONE: AREA 704  
373-4083

Mr. Norman C. Moseley, Director  
U. S. Nuclear Regulatory Commission  
Suite 818  
230 Peachtree Street, Northwest  
Atlanta, Georgia 30303



Re: Oconee Unit 3  
Docket No. 50-287

Dear Mr. Moseley:

My letter of November 13, 1975, transmitted Unusual Event Report UE-287/75-10, concerning a weld failure on a sample line from the 3A Low Pressure Injection System Cooler. The following provides additional information relating to this incident and associated corrective action.

The Corrective Action Section of UE-287/75-10 specified that representative welds in each Oconee unit would be dye penetrant tested to determine deleterious effects which may have been caused by vibration in the LPI trains. The welds listed in Units 1 and 2 were determined to be acceptable. For Unit 3, nine welds were tested, including one in each plane that would be affected by vibration, and the welds were determined to be acceptable with one exception. This weld had previously failed (refer to Abnormal Occurrence Report AO-287/74-6) and was on the same 3/4" sample line as the weld failure addressed by UE-287/75-10. Subsequently, this weld, and its adjacent line and valve, into which the crack extended, were replaced.

Very truly yours,

*W. O. Parker, Jr.*  
William O. Parker, Jr. *By [Signature]*

EDB:ge

cc: Mr. Benard C. Rusche ✓



14091