

NUCLEAR REGULATORY

Mail Section



TELEPHONE AREA 704

373-4083

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242


WILLIAM O. PARKER, JR. VICE PRESIDENT STEAM PRODUCTION

June 10, 1976

OCKETED

Mr. Benard C. Rusche Director of Nuclear Reactor U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Oconee Nuclear Station Docket Nos. 50-269, -270, -287



At present, the Oconee 1 suppressors of the type identified have been repaired or replaced. This work is also in progress on Oconee 2 and will be completed before its startup in late June, 1976. However, necessary material to complete the Unit 3 repairs is not available for a scheduled outage beginning June 20, 1976. Therefore, the outage has been rescheduled to begin not later than July 4, 1976 in order to allow additional time to expedite material delivery. It is considered that the rescheduling of this outage of Oconee 3 will not be inimical to the health and safety of the public.

June 20, 1976 for replacement of these suppressors.

truly yours

William O. Parker,

MST:vr

cc: Mr. Norman C. Moseley