



EXPLANATION

- | | |
|--|--|
| 1960 - 1976 EARTHQUAKE EPICENTERS | 1977 - 1981 EARTHQUAKE EPICENTERS |
| ● MM-INTENSITY IV OR LESS | ▲ MM-INTENSITY IV OR LESS |
| ● MM-INTENSITY V - VI | ▲ MM-INTENSITY V |
| ● MM-INTENSITY VII | |

COPYRIGHT © 2015 BURNS & MCDONNELL ENGINEERING COMPANY, INC.

Source: Modified from Burchett, R.R., et al, Oklahoma Geological Survey, 1985. Special Publication 85-2, Seismicity and Tectonic Relationships of the Nemaha Uplift and Midcontinent Geophysical Anomaly (Final Project Summary).

	<p>Figure 2-6 LOCATIONS OF FAULTS AND MAGNITUDES OF EARTHQUAKES IN OKLAHOMA DECOMMISSIONING PLAN CIMARRON SITE, OKLAHOMA</p>
--	--