

**UNIVERSAL CONSULTANTS, INC.
MEDICAL PHYSICS SURVEY REPORT
SEALED SOURCE LEAK TEST ANALYSIS REPORT**

FACILITY: Cardiovascular Associates of the Virgin Islands, PLLC

Analysis of the WIPE used to conduct a leak test on the sealed sources identified below was performed by gas or scintillation detection and revealed removable contamination was less than 0.005 uCi, unless otherwise noted when compared against NIST traceable standards.

SOURCE: Cs-137, Mfg IPL, Model RV-137-200U, SN# 1452-32-11, 10/01/2010, 197.7 uCi

Date: 12/16/2015

Wipe No: 19790

Gross Wipe CPM: 104

Background CPM: 95

Net CPM: 9

CPM: for 0.005 uCi: 2652

Analyst:

Performed by: Universal Consultants, Inc. Ohio License #03225480006

RETAIN THIS RECORD IN COMPLIANCE WITH 10 CFR 35.59 (d)

RSO SIGNATURE: _____

UNIVERSAL CONSULTANTS, INC.
MEDICAL PHYSICS SURVEY REPORT
SEALED SOURCE LEAK TEST ANALYSIS REPORT

FACILITY: Cardiovascular Associates of the Virgin Islands, PLLC

Analysis of the WIPE used to conduct a leak test on the sealed sources identified below was performed by gas or scintillation detection and revealed removable contamination was less than 0.005 uCi, unless otherwise noted when compared against NIST traceable standards.

SOURCE: Co-57, Mfg IPL, Model NES392, SN# 1455-016, 4/1/2011, 10 mCi

Date: 12/16/2015

Wipe No: 19788

Gross Wipe CPM: 104

Background CPM: 95

Net CPM: 9

CPM: for 0.005 uCi: 6682

Analyst:

SOURCE: Co-57, Mfg IPL, Model RV-057-5M, SN# 1461-35-9, 3/1/2011, 5.727 mCi

Date: 12/16/2015

Wipe No: 19789

Gross Wipe CPM: 104

Background CPM: 95

Wipe CPM: 9

CPM: for 0.005 uCi: 6682

Analyst:

Performed by: Universal Consultants, Inc. Ohio License #03225480006

RETAIN THIS RECORD IN COMPLIANCE WITH 10 CFR 35.2067

RSO SIGNATURE: _____