

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

<p>1. LICENSEE/LOCATION INSPECTED:  Mistras Group, Inc. 161 Tower Drive, Suite E Burr Ridge, IL 60527 Location Inspected: Anchorage, AK  REPORT NUMBER(S) 2016-001</p>	<p>2. NRC/REGIONAL OFFICE  Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352</p>
--	---

<p>3. DOCKET NUMBER(S)  030-35114</p>	<p>4. LICENSE NUMBER(S)  12-16559-02</p>	<p>5. DATE(S) OF INSPECTION  February 11, 2016</p>
---	--	--

**LICENSEE:**  
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ✓ 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.  
(Violations and Corrective Actions)

**Statement of Corrective Actions**

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	James L. Thompson	<i>James L. Thompson</i> RR 51	3/6/16
BRANCH CHIEF	Aaron McCraw	<i>Aaron McCraw</i>	3/7/16

**Docket File Information**  
**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:  Mistras Group, Inc. 161 Tower Drive, Suite E Burr Ridge, IL 60527 Location Inspected: Anchorage, AK  REPORT NUMBER(S) 2016-001	2. NRC/REGIONAL OFFICE  Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
--	---

3. DOCKET NUMBER(S)  030-35114	4. LICENSE NUMBER(S)  12-16559-02	5. DATE(S) OF INSPECTION  February 11, 2016
--------------------------------------	---	---

6. INSPECTION PROCEDURES USED  87121, 87137	7. INSPECTION FOCUS AREAS  Operations at Field Office
---	---

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S) 03320	2. PRIORITY 1	3. LICENSEE CONTACT Daryl Istre, RSO	4. TELEPHONE NUMBER (281) 478-1643
-----------------------------	------------------	---	---------------------------------------

Main Office Inspection                              Next Inspection Date:    No Change  
  
 Field Office Inspection    2410 Azurite Court, Suite B, Anchorage, AK  
  
 Temporary Job Site Inspection \_\_\_\_\_

**PROGRAM SCOPE**

This was an unannounced inspection of a non-destructive testing company authorized to use radioactive material for industrial radiography at numerous field stations and at temporary job sites throughout NRC jurisdiction. This inspection was limited to observations at a field office in Anchorage, Alaska, as an assist inspection for Region III.

The inspector arrived on-site and spoke with the only licensee employee on site, Mr. Kelly Morris, an Advanced Services Specialist. He designs and services X-ray tubes used for the crawlers. He stated that about 4 months ago, all licensed material was transferred to the North Slope field office at Prudhoe Bay. NSTS records show that this occurred as stated and that all licensed material is now at Prudhoe Bay.

A confirmatory survey was performed at the storage vault in Anchorage, and all results were equivalent to background radiation levels. All equipment use information and records were transferred to the North Slope as well. The licensee is unsure of whether they will return to the Anchorage location after the winter months, or simply remove the Anchorage field office from their license.

No violations of NRC requirements were identified as a result of this inspection.