



Br. 1

January 29, 2016

License No: 52-25531-01
Control No: 573484 (Reference) RLT 03035451

REC RG 1 03 08 16 AM 07 02

Division of Nuclear Materials Safety
NRC Region I
2100 Renaissance Blvd, Suite 100
King of Prussia, Penn 19406-2713

RE: Change of Location of Hot Room within the same Department and closing of previous Hot Room

Dear Sir or Madam:

This letter is to inform that there has been a change of location of the Hot Room within the same Department. The previous Hot Room location has been closed as of December 9, 2015.

All radioactive sources have been inventoried and removed from old storage area and transferred to the new area. The documents are located in the Leak Test and Inventory records of the sources. These documents will be available for NRC inspection in next visit.

Included is the Closed-out survey and the layout of the new Hot Room. The address remains the same.

If you have any question regarding this matter, please feel free to contact me at (787) 949-2011.

Sincerely,

Elba Orduña-Acúm, MD
Radiation Safety Officer



**DOCTORS'
CENTER
HOSPITAL**

Close Out

Daily Survey

Closing Survey

x11.9.15
4:00pm

Date	Door handle 1	Floor 2	Counter Top 3	Counter Top 4	Floor 5	Door handle 6	Counter Top 7	Floor 8	Fume Hood	Check Source	Hands	Initials	Comments
x11.9.15	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.21	0.6	OK	ych	Tech

*90% done
RSO*


Weekly Lab Survey

x11.9.15	0	0	0	0	0	0	0	0	0		Well Counter	OK	ych	
											Well Counter			
											Well Counter			
											Well Counter			
											Well Counter			

Meter Used: Ludlum Model: 14C S/N #: 129630 Well Counter CRC-551W System S/N 550032

*WC Background 0.03cpm
Water Bkg 0.03mR/hr
Trigger Bkg for both 2* Bkg*

Nuclear Medicine Department
 Doctors' Center Hospital
 Bayamón, PR



This is to acknowledge the receipt of your letter/application dated

January 29, 2016, and to inform you that the initial processing which includes an administrative review has been performed.

Amendment (52-25531-01)
There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number** 590417.
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.