

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: District Hospital Partners, L.P. d/b/a The George Washington University Hospital 900 23 rd Street, N.W. Washington, D.C. 20037 REPORT NUMBER 2016-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713
3. DOCKET NUMBER 030-35424	4. LICENSE NUMBER 08-30607-01	5. DATES OF INSPECTION February 16-17, 2016

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☐ 1. Based on the inspection findings, no violations were identified.
- ☒ 2. Previous violation closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.



Non-cited violation(s) were discussed involving the following requirement(s) and corrective action(s):

- ☒ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)

Continued on page 2

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Kimberly Russo	KRS	3/17/16
NRC INSPECTOR	Shawn Seeley		3/9/16
BRANCH CHIEF	James P. Dwyer		3/21/16

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED; District Hospital Partners, L.P. d/b/a The George Washington University Hospital 900 23 rd Street, N.W. Washington, D.C. 20037 REPORT NUMBER 2016-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713
3. DOCKET NUMBER 030-35424	4. LICENSE NUMBER 08-30607-01	5. DATES OF INSPECTION February 16-17, 2016

(Continued from Page 1)

10 CFR 35.70 states, in part, that in addition to the surveys required by Part 20, a licensee shall survey with a survey instrument at the end of the day of use.

Contrary to the above, February 16, 2016, the licensee failed to survey all areas where unsealed byproduct material requiring a written directive was prepared for use or administered with a radiation detection survey instrument at the end of each day of use. Specifically, the licensee conducted the surveys at the beginning of the day prior to use of the material.

This is a Severity Level IV Violation (Enforcement policy example: Section 6.7.d)

The licensee implemented corrective actions that included: retraining all personnel in the expectations for daily surveys at the end of each day of use in accordance with NRC regulations.