

The Church of Jesus Christ of Latter-day Saints
SHARON VT FM GROUP
273 LDS Lane
South Royalton, VT 05068
PHONE: (802) 763-8198* FAX: (802) 763-8199 * CELL: (603) 252-6566

February 9, 2016

Director of FSME
Attn: GLTS
USNRC
Washington, DC 20555-0001

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on February 1, 2016 we transferred the self-luminous exit signs listed on the attached spreadsheet to SRBT, 320 Boundary Rd., Suite 140, Pembroke, Ontario, K8A 6W5, Canada with CNSC License #NSPFOL-13.00/2022. As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please contact Joseph Mender at 802-763-8198 or his cell number 603-252-6566.

Sincerely,



Joseph Mender
Certified Facilities Manager

Encl.

SERIAL NUMBER SPREADSHEET

Company Name	Sharon, VT FM Group	Date	10/28/15
Address 1	5431 Route 5	Isolite RMA #	
Address 2		EWS Order #	909259211, 909401843
Address 3		MTS Order #s	2430100940, FMACQ-
City/State	Ascutway, VT	Contact Name	David Beers 172684
Zip/Post Code	05030	Contact Phone	603-762-1175
Country	USA	Contact FAX	802-763-8199
		Contact E-mail	dbeers@ldschurch.org

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"
				Month	Year	
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15	SRB Tech	SRB Tech B100	544664	7	92	20"ci" curies
	SRB Tech	B100	544677	miss	illegible	20"ci" curies
	SRB Tech	B100	544672	7	92	20"ci"
	SRB Tech	B100	544675	7	92	20"ci"
	SRB Tech	B100	544669	7	92	20"ci"
	SRB Tech	B100	544679	7	92	20"ci"
	SRB Tech	B100	544665	7	92	20"ci"
	SRB Tech	B100	544680	7	92	20 ci
	SRB Tech	B100	544676	7	92	20 ci
	SRB Tech	B100	544678	7	92	20 ci
	SRB Tech	B100	544666	7	92	20 ci
	SRB Tech	B100	544673	7	92	20 ci
	SRB Tech	B100	544674	7	92	20 ci
	SRB Tech	B100	544670	7	92	20 ci
	SRB Tech	B100	544668	7	92	20 ci

*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

Page 1

SERIAL NUMBER SPREADSHEET

Company Name	Sharon VT FM Group	Date	10/28/15
Address 1	25431 Route 5	Isolite RMA #	
Address 2		EWS Order #	909259211, 909401843
Address 3		MTS Order #s	2430100940, FM ACQ-
City/State	Ascutney, VT	Contact Name	David Beers 172682
Zip/Post Code	05030	Contact Phone	603 762 1175
Country	USA	Contact FAX	802-762-8199
		Contact E-mail	dbeers@ldschurch.org

Addition

22
4

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "CI" or "TBq"
				Month	Year	
1	Isolite	2000	A821448	2	98	11.5 CI
2	Isolite	2000	A821444	2	98	11.5 CI
3	Isolite	2000	A821445	2	98	11.5 CI
4	Isolite	2000	A821446	2	98	11.5 CI
5	Isolite	2000	A821447	2	98	11.5 CI
6	SRB Tech	B100	577526	2	94	20 CI
7	SRB Tech	B100	577527	2	94	20 "CI"
8						
9						
10						
11						
12						
13						
14						
15						

**The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.*

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

Page 2

SERIAL NUMBER SPREADSHEET

Company Name	Shaion, VT FM Group	Date	10/28/15
Address 1	637 N. Shrewsbury Rd	Isolite RMA #	
Address 2		EWS Order #	909379702
Address 3		MTS Order #s	2430104201
City/State	North Clarendon, VT	Contact Name	David Beers
Zip/Post Code	05759	Contact Phone	803-762-1175
Country	USA	Contact FAX	802-763-8199
		Contact E-mail	dbeers@kdschurch.org

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "CI" or "TBq"
				Month	Year	
1	SRB Tech	B100	516706	8	90	20" ci"
2	SRB Tech	B100	516708	8	90	20" ci"
3	SRB Tech	B100	516704	8	90	20" ci"
4	SRB Tech	B100	516707	8	90	20" ci"
5	SRB Tech	B100	516703	8	90	20" ci"
6	SRB Tech	B100	516709	8	90	20" ci"
7	SRB Tech	B100	516705	8	90	20" ci"
8	SRB Tech	B100	516701	8	90	20" ci"
9	SRB Tech	B100	516699	8	90	20" ci"
10	SRB Tech	B100	516698	8	90	20" ci"
11	SRB Tech	B100	516700	8	90	20" ci"
12	SRB Tech	B100	516702	8	90	20" ci"
13						
14						
15						

*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.