



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
1600 E. LAMAR BLVD
ARLINGTON TX 76011-4511

May 2, 2016

Mr. Bryan McDonald, President
Audubon Field Solutions, LLC
10205 Westheimer Road, Suite 100
Houston, TX 77042

SUBJECT: REQUEST FOR ADDITIONAL INFORMATION

Dear Mr. McDonald:

The Nuclear Regulatory Commission (NRC) has received your response letter dated April 27, 2016, and additional information is needed. Please provide the following information in a signed and dated letter, in company letterhead, within 20 days from receipt of this letter, and make reference to mail control number 590527.

1. Page B-1 of Appendix B of NUREG-1556, Volume 1, Revision 1, did not provide sufficient information to determine the number of gauges that need to be authorized in the NRC license. Indicate the number of Troxler 3400 Series portable nuclear gauges that your company wants authorized in the NRC license.
2. Page B-5 was not included in your response letter. Complete Page B-5 of Appendix B of NUREG-1556, Volume 1, revision 1, and make the appropriate commitments for routine cleaning and lubrication, and non-routine maintenance by checking both boxes.
3. The license application dated March 17, 2016 lists the storage location as 418 Mayo Street, Clarksburg, West Virginia, while the response letter dated April 27, 2016 provides a diagram for a storage location at 502 Werninger Street, Clarksburg, West Virginia. Indicate which storage location should be listed in the NRC license.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the NRC's Agencywide Documents Access and Management System (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>.

Thank you for your cooperation.

Sincerely,

/RA/

Roberto J. Torres, M.S., Senior Health Physicist
Nuclear Materials Safety Branch B

Docket: 030-38915
Control: 590527