

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

SESSION NBR: 8810040252 DOC. DATE: 88/09/20 NOTARIZED: NO DOCKET #
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co. 05000269
 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co. 05000270
 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co. 05000287

AUTH. NAME AUTHOR AFFILIATION
 COLLINS, D.M. Region 2, Ofc of the Director
 RECIP. NAME RECIPIENT AFFILIATION
 TUCKER, H.B. Duke Power Co.

SUBJECT: Forwards Insp Repts 50-269/88-24, 50-270/88-24 & 50-287/88-24 on 880822-26. No violations or deviations noted.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2 + 11
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES: AEOD/Ornstein:1cy. 05000269 S
 AEOD/Ornstein:1cy. 05000270
 AEOD/Ornstein:1cy. 05000287 /

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
	PD2-3 PD	1 1	PASTIS, H	2 2
INTERNAL:	ACRS	2 2	AEOD	1 1
	DEDRO	1 1	NRR MORISSEAU, D	1 1
	NRR/DLPQ/PEB 11	1 1	NRR/DLPQ/QAB 10	1 1
	NRR/DOEA DIR 11	1 1	NRR/DREP/EPB 10	1 1
	NRR/DREP/RPB 10	2 2	NRR/DRIS DIR 9A	1 1
	NRR/PMAS/ILRB12	1 1	NUDOCS-ABSTRACT	1 1
	OE LIEBERMAN, J	1 1	OGC/HDS2	1 1
	REG FILE 02	1 1	RES/DSIR DEPY	1 1
	RGN2 FILE 01	1 1		
EXTERNAL:	LPDR	1 1	NRC PDR	1 1
	NSIC	1 1		

NOTES: 1 1

R
I
D
S
/
A
D
D
S

official

SEP 20 1988

Docket Nos. 50-269, 50-270, 50-287
License Nos. DPR-38, DPR-47, DPR-55

Duke Power Company
ATTN: Mr. H. B. Tucker, Vice President
Nuclear Production Department
422 South Church Street
Charlotte, NC 28242

Gentlemen:

SUBJECT: INSPECTION REPORT NOS. 50-269/88-24, 50-270/88-24 AND 50-287/88-24

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by S. S. Adamovitz on August 22-26, 1988. The inspection included a review of activities authorized for your Oconee facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

*original signed by
T. Decker for*

Douglas M. Collins, Chief
Emergency Preparedness and
Radiological Protection Branch
Division of Radiation Safety
and Safeguards

Enclosure: (See page 2)

8810040252 880920
PDR ADOCK 05000269
Q FDC

11
1E01

Duke Power Company

2

Enclosure:
Inspection Report

cc w/encl:
M. S. Tuckman, Station Manager
State of South Carolina

bcc w/encl:
NRC Resident Inspector
DRS Technical Assistant
H. Pastis, NRR
Document Control Desk

RII
SA
SAdamovitz
9/19/88

RII
JK
JKahle
9/19/88

RII
TP
TPeebles
9/20/88